

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S1080                                             | 3334           | Allen Av           | Building        | c 1968      | Domestic-single      | Italian Ren Rev     | 2              | Brick           | Low             |
| PF.M06.S1081                                             | 3400           | Allen Av           | Building        | c 1967      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S1082                                             | 3406           | Allen Av           | Building        | c 1968      | Domestic-single      | Col Revival/Ranch   | 1 to 2         | Brick           | Low             |
| PF.M06.S1079                                             | 3407           | Allen Av           | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1078                                             | 3413           | Allen Av           | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1 to 2         | Brick           | Low             |
| PF.M06.S1083                                             | 3416           | Allen Av           | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M03.S0615                                             | 100 blk        | Alpine Dr          | Structure       | c 1955      | Infrastructure       | No Style            | None           | Conc            | Medium          |
| PF.M03.S0569                                             | 101            | Alpine Dr          | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0570                                             | 111            | Alpine Dr          | Building        | c 1959      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0567                                             | 116            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M03.S0571                                             | 117            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0568                                             | 110            | Alpine Dr          | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0566                                             | 200            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0574                                             | 200 blk        | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0572                                             | 203            | Alpine Dr          | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0565                                             | 206            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0573                                             | 211            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0564                                             | 218            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0563                                             | 224            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0575                                             | 227            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0562                                             | 300            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0576                                             | 301            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0577                                             | 307            | Alpine Dr          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0561                                             | 316            | Alpine Dr          | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1330                                             | 114            | Amherst St         | Building        | c 1965      | Domestic-multiple    | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1343                                             | 300 blk        | Amherst St         | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1354                                             | 311            | Amherst St         | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1353                                             | 319            | Amherst St         | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1344                                             | 320            | Amherst St         | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1345                                             | 324            | Amherst St         | Building        | c 1955      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Low             |
| PF.M05.S1352                                             | 325            | Amherst St         | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1351                                             | 409            | Amherst St         | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1350                                             | 415            | Amherst St         | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1349                                             | 421            | Amherst St         | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1348                                             | 501            | Amherst St         | Building        | c 1957      | Domestic-single      | PW Modern/Ranch     | 1              | Brick           | Low             |
| PF.M05.S1347                                             | 509            | Amherst St         | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1346                                             | 515            | Amherst St         | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1178                                             | 700 blk        | Amherst St         | Building        | c 1960      | Religious-church     | Post-war Modern     | 1 to 2         | Brick           | Low             |
| PF.M05.S1179                                             | 709            | Amherst St         | Building        | c 1960      | Unknown              | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1180                                             | 719            | Amherst St         | Building        | c 1959      | Unknown              | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1125                                             | 1000 blk       | Amherst St         | Structure       | c 1962      | Infrastructure       | No style            | None           | Stone           | Medium          |
| PF.M06.S1108                                             | 1008           | Amherst St         | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1124                                             | 1009           | Amherst St         | Building        | c 1970      | Domestic-single      | No style            | 1.5            | Brick           | Low             |
| PF.M06.S1123                                             | 1015           | Amherst St         | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1109                                             | 1016           | Amherst St         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1.5            | Brick           | Low             |
| PF.M06.S1122                                             | 1023           | Amherst St         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1110                                             | 1024           | Amherst St         | Building        | c 1964      | Domestic-single      | FCR/Ranch           | 1              | Brick           | Medium          |
| PF.M06.S1121                                             | 1029           | Amherst St         | Building        | c 1963      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M06.S1111                                             | 1030           | Amherst St         | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1120                                             | 1101           | Amherst St         | Building        | c 1963      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S1119                                             | 1107           | Amherst St         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1112                                             | 1110           | Amherst St         | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S1068                                             | 1113           | Amherst St         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1.5            | Brick           | Medium          |
| PF.M08.S1592                                             | 1024           | Arlington Av       | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1586                                             | 1101           | Arlington Av       | Building        | c 1960      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1591                                             | 3716           | Arlington Av       | Building        | c 1962      | Domestic-single      | No style            | 1.5            | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1590                                             | 3721           | Arlington Av       | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1589                                             | 3809           | Arlington Av       | Building        | 1958        | Domestic-single      | PW Modern/Ranch     | 1              | Brick           | High            |
| PF.M08.S1588                                             | 3815           | Arlington Av       | Building        | c 1960      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1587                                             | 3821           | Arlington Av       | Building        | 1960        | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M03.S0481                                             | 2804           | Bain Pl            | Building        | c 1952      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0475                                             | 2805           | Bain Pl            | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M03.S0476                                             | 2809           | Bain Pl            | Building        | c 1950      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0480                                             | 2812           | Bain Pl            | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0477                                             | 2817           | Bain Pl            | Building        | c 1950      | Domestic-single      | Col Revival         | 1              | Brick           | Medium          |
| PF.M03.S0479                                             | 2818           | Bain Pl            | Building        | c 1950      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0478                                             | 2825           | Bain Pl            | Building        | c 1950      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M03.S0470                                             | 2910           | Bain Pl            | Building        | c 1958      | Domestic-single      | Ranch               | 1 to 2         | Brick           | Low             |
| PF.M03.S0471                                             | 2911           | Bain Pl            | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M03.S0469                                             | 2918           | Bain Pl            | Building        | c 1960      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M03.S0472                                             | 2919           | Bain Pl            | Building        | c 1961      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M03.S0468                                             | 2926           | Bain Pl            | Building        | c 1960      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M03.S0473                                             | 2927           | Bain Pl            | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0467                                             | 2934           | Bain Pl            | Building        | c 1964      | Domestic-single      | Ranch               | 1.5            | Brick           | Low             |
| PF.M03.S0474                                             | 2935           | Bain Pl            | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1181                                             | 3314           | Bain Pl            | Building        | c 1956      | Domestic-single      | No style            | 1              | Wood            | Low             |
| PF.M05.S1186                                             | 3315           | Bain Pl            | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1182                                             | 3318           | Bain Pl            | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1185                                             | 3319           | Bain Pl            | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1183                                             | 3324           | Bain Pl            | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1184                                             | 3325           | Bain Pl            | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1198                                             | 3414           | Bain Pl            | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1215                                             | 3415           | Bain Pl            | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1199                                             | 3424           | Bain Pl            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1214                                             | 3425           | Bain Pl            | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M05.S1213                                             | 3431           | Bain Pl            | Building        | c 1969      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1200                                             | 3432           | Bain Pl            | Building        | c 1968      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1201                                             | 3502           | Bain Pl            | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1212                                             | 3505           | Bain Pl            | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1202                                             | 3514           | Bain Pl            | Building        | c 1955      | Domestic-single      | No style            | 1 to 2         | Brick           | Low             |
| PF.M05.S1211                                             | 3515           | Bain Pl            | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1203                                             | 3518           | Bain Pl            | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1210                                             | 3521           | Bain Pl            | Building        | c 1954      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1204                                             | 3524           | Bain Pl            | Building        | c 1957      | Domestic-single      | Post-war Modern     | 1              | Brick           | Medium          |
| PF.M05.S1209                                             | 3525           | Bain Pl            | Building        | c 1958      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1205                                             | 3600           | Bain Pl            | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1208                                             | 3601           | Bain Pl            | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1206                                             | 3610           | Bain Pl            | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1207                                             | 3611           | Bain Pl            | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1494                                             | 3700           | Bain Pl            | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M07.S1496                                             | 3700 blk       | Bain Pl            | Structure       | c 1957      | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M07.S1491                                             | 3701           | Bain Pl            | Building        | c 1958      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1494                                             | 3710           | Bain Pl            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1492                                             | 3711           | Bain Pl            | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M07.S1493                                             | 3721           | Bain Pl            | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0212                                             | 600 blk        | Barbara St         | Building        | c 1946      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0248                                             | 600 blk        | Barbara St         | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |
| PF.M01.S0249                                             | 614            | Barbara St         | Building        | c 1946      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M03.S0213                                             | 621            | Barbara St         | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |
| PF.M03.S0214                                             | 625            | Barbara St         | Building        | c 1946      | Domestic-single      | Colonial Revival    | 1              | Asbes           | Low             |
| PF.M01.S0247                                             | 626            | Barbara St         | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |
| PF.M01.S0246                                             | 630            | Barbara St         | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M03.S0215                                             | 633            | Barbara St         | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M01.S0245                                             | 634            | Barbara St         | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Medium          |
| PF.M01.S0244                                             | 702            | Barbara St         | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M03.S0216                                             | 703            | Barbara St         | Building        | c 1951      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |
| PF.M01.S0243                                             | 708            | Barbara St         | Building        | c 1952      | Domestic-single      | Min Traditional   | 1              | Brick           | Medium          |
| PF.M03.S0217                                             | 709            | Barbara St         | Building        | c 1946      | Domestic-single      | Min Traditional   | 1              | Brick           | Medium          |
| PF.M01.S0218                                             | 717            | Barbara St         | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0242                                             | 718            | Barbara St         | Building        | c 1970      | Domestic-single      | Neo-Med           | 1              | Brick           | Low             |
| PF.M01.S0219                                             | 719            | Barbara St         | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0241                                             | 724            | Barbara St         | Building        | c 1952      | Domestic-single      | Ranch             | 1              | Conc blk        | Medium          |
| PF.M01.S0240                                             | 728            | Barbara St         | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0220                                             | 729            | Barbara St         | Building        | c 1951      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0239                                             | 734            | Barbara St         | Building        | c 1950      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M01.S0221                                             | 735            | Barbara St         | Building        | c 1951      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0238                                             | 802            | Barbara St         | Building        | c 1949      | Domestic-single      | Min Traditional   | 1              | Brick           | Low             |
| PF.M01.S0222                                             | 803            | Barbara St         | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0237                                             | 806            | Barbara St         | Building        | c 1950      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0223                                             | 811            | Barbara St         | Building        | c 1951      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0236                                             | 814            | Barbara St         | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0224                                             | 817            | Barbara St         | Building        | c 1951      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0235                                             | 904            | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0225                                             | 905            | Barbara St         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0234                                             | 910            | Barbara St         | Building        | c 1952      | Domestic-single      | Min Traditional   | 1              | Brick           | Low             |
| PF.M01.S0226                                             | 911            | Barbara St         | Building        | c 1953      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0233                                             | 920            | Barbara St         | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0227                                             | 921            | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0232                                             | 1002           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M02.S0228                                             | 1007           | Barbara St         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M02.S0231                                             | 1010           | Barbara St         | Building        | c 1953      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M02.S0230                                             | 1022           | Barbara St         | Building        | c 1960      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M02.S0229                                             | 1023           | Barbara St         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0403                                             | 1105           | Barbara St         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M02.S0402                                             | 1106           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M02.S0401                                             | 1114           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0404                                             | 1115           | Barbara St         | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0400                                             | 1120           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0399                                             | 1204           | Barbara St         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0405                                             | 1205           | Barbara St         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M02.S0398                                             | 1214           | Barbara St         | Building        | c 1952      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M02.S0406                                             | 1215           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0397                                             | 1220           | Barbara St         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0396                                             | 1316           | Barbara St         | Building        | c 1952      | Religious-church     | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M02.S0407                                             | 1319           | Barbara St         | Building        | c 1953      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M02.S0408                                             | 1405           | Barbara St         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0079                                             | 2213           | Bateman Av         | Building        | c 1938      | Domestic-single      | Col Revival       | 2              | Wood            | Low             |
| PF.M01.S0077                                             | 2217           | Bateman Av         | Building        | c 1932      | Domestic-auxiliary   | Tudor Revival     | 1              | Brick           | Medium          |
| PF.M01.S0317                                             | 2300 blk       | Bateman Av         | Building        | c 1932      | Domestic-single      | No style          | 1              | Stone           | Low             |
| PF.M01.S1728                                             | 2305           | Bateman Av         | Building        | c 1968      | Domestic-single      | Post-war Modern   | 1              | Brick           | Low             |
| PF.M01.S0316                                             | 2311           | Bateman Av         | Building        | c 1935      | Domestic-single      | Tudor Revival     | 1              | Stone           | Medium          |
| PF.M01.S0318                                             | 2403           | Bateman Av         | Building        | c 1938      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M01.S0319                                             | 2407           | Bateman Av         | Building        | c 1938      | Domestic-single      | Tudor Revival     | 1              | Brick           | Low             |
| PF.M01.S0320                                             | 2413           | Bateman Av         | Building        | c 1935      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0321                                             | 2419           | Bateman Av         | Building        | c 1937      | Domestic-single      | Colonial Revival  | 1.5            | Brick           | Low             |
| PF.M01.S0322                                             | 2503           | Bateman Av         | Building        | c 1948      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0323                                             | 2509           | Bateman Av         | Building        | c 1939      | Domestic-single      | Colonial Revival  | 2              | Brick           | Medium          |
| PF.M01.S0324                                             | 2515 AB        | Bateman Av         | Building        | c 1953      | Domestic-duplex      | Colonial Revival  | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0325                                             | 2521 AB        | Bateman Av         | Building        | c 1954      | Domestic-duplex      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M01.S0326                                             | 2617           | Bateman Av         | Building        | c 1932      | Domestic-single      | Not Visible        | 1              | Stone           | Medium          |
| PF.M01.S0327                                             | 2623           | Bateman Av         | Building        | c 1936      | Domestic-single      | No style           | 1 to 2         | Vinyl           | Low             |
| PF.M01.S0328                                             | 2629           | Bateman Av         | Building        | c 1946      | Domestic-single      | Colonial Revival   | 1              | Wood            | Medium          |
| PF.M03.S0504                                             | 2803           | Bateman Av         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Vinyl           | Low             |
| PF.M03.S0510                                             | 2806           | Bateman Av         | Building        | c 1950      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M03.S0505                                             | 2811           | Bateman Av         | Building        | c 1952      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M03.S0509                                             | 2816           | Bateman Av         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1 to 2         | Brick           | Medium          |
| PF.M03.S0506                                             | 2817           | Bateman Av         | Building        | c 1953      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M03.S0507                                             | 2823           | Bateman Av         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M03.S0508                                             | 2829           | Bateman Av         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M08.S1585                                             | 4100 blk       | Beall Cir          | Structure       | c 1964      | Infrastructure       | No style           | None           | Conc            | Medium          |
| PF.M08.S1582                                             | 4101           | Beall Cir          | Building        | c 1970      | Domestic-single      | Col Revival/Crafts | 1              | Brick           | Low             |
| PF.M08.S1583                                             | 4104           | Beall Cir          | Building        | c 1965      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M08.S1746                                             | 4108           | Beall Cir          | Site            | c 1800s     | Landscape            | No style           | None           | None            | Medium          |
| PF.M08.S1581                                             | 4115           | Beall Cir          | Building        | c 1964      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M08.S1584                                             | 4116           | Beall Cir          | Building        | c 1964      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M04.S0792                                             | 2812           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M04.S0818                                             | 2813           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | PW Modern/Ranch    | 1              | Brick           | High            |
| PF.M04.S0817                                             | 2821           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M04.S0793                                             | 2822           | Birdwell Dr        | Building        | c 1953      | Domestic-single      | CR/Ranch/PWMod     | 1              | Brick           | Medium          |
| PF.M04.S0794                                             | 2826           | Birdwell Dr        | Building        | c 1953      | Domestic-single      | Ranch/PW Modern    | 1              | Brick           | Low             |
| PF.M04.S0816                                             | 2827           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M04.S0795                                             | 2902           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch              | 1              | Wood            | Medium          |
| PF.M04.S0815                                             | 2903           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M04.S0796                                             | 2910           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Low             |
| PF.M04.S0814                                             | 2911           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M04.S0797                                             | 2920           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0813                                             | 2923           | Birdwell Dr        | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0798                                             | 2928           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0812                                             | 2931           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0799                                             | 2932           | Birdwell Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0811                                             | 3003           | Birdwell Dr        | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0810                                             | 3007           | Birdwell Dr        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0809                                             | 3101           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0800                                             | 3106           | Birdwell Dr        | Building        | c 1957      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0808                                             | 3107           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0807                                             | 3115           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0801                                             | 3120           | Birdwell Dr        | Building        | c 1965      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0806                                             | 3125           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | High            |
| PF.M04.S0802                                             | 3126           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Col Rev/PWM       | 1              | Brick           | Low             |
| PF.M06.S1741                                             | 3200 blk       | Birdwell Dr        | Structure       | c 2010      | Infrastructure       | No style          | None           | Wood            | Medium          |
| PF.M04.S0805                                             | 3205           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0803                                             | 3210           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0804                                             | 3215           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | High            |
| PF.M06.S0923                                             | 3227           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0924                                             | 3237           | Birdwell Dr        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0926                                             | 3240           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0925                                             | 3241           | Birdwell Dr        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival | 1-1.5          | Brick           | Medium          |
| PF.M06.S0933                                             | 3400           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0932                                             | 3400 blk       | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M06.S0934                                             | 3408           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0935                                             | 3416           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0936                                             | 3500           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0931                                             | 3505           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M06.S0937                                             | 3510           | Birdwell Dr        | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0938                                             | 3518           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0939                                             | 3600           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M06.S0930                                             | 3601           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0940                                             | 3604           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0929                                             | 3607           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0941                                             | 3614           | Birdwell Dr        | Building        | c 1956      | Domestic-single      | Col Revival         | 1              | Brick           | Medium          |
| PF.M08.S1718                                             | 3701           | Birdwell Dr        | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1717                                             | 3710           | Birdwell Dr        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1707                                             | 3801           | Birdwell Dr        | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S0892                                             | 1800           | Blossom Ln         | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S0897                                             | 1801           | Blossom Ln         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0893                                             | 1808           | Blossom Ln         | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0896                                             | 1809           | Blossom Ln         | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0894                                             | 1816           | Blossom Ln         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0895                                             | 1817           | Blossom Ln         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0616                                             | 2700           | Broadway           | Building        | c 1937      | Commerce/Trade       | No Style            | 1              | Vinyl           | Low             |
| PF.M07.S1745                                             | 3928           | Broadway           | Building        | c 1966      | Commerce/Trade       | No style            | 1              | Brick           | Low             |
| PF.M07.S1526                                             | 4002           | Broadway           | Building        | c 1964      | Commercial-office    | No style            | 1              | Brick           | Low             |
| PF.M07.S1525                                             | 4202           | Broadway           | Building        | 1963        | Religious-church     | Neo-Classical       | 1              | Brick           | Low             |
| PF.M07.S1449                                             | 300 blk        | Brookwood Cir      | Structure       | c 1965      | Infrastructure       | No style            | None           | Conc            | Low             |
| PF.M07.S1446                                             | 322            | Brookwood Cir      | Building        | c 1970      | Domestic-single      | No style            | 1              | Brick           | Low             |
| PF.M07.S1445                                             | 325            | Brookwood Cir      | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1447                                             | 326            | Brookwood Cir      | Building        | c 1970      | Domestic-single      | Ranch/Neo-Med       | 1              | Brick           | Low             |
| PF.M07.S1444                                             | 327            | Brookwood Cir      | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1448                                             | 328            | Brookwood Cir      | Building        | c 1968      | Domestic-single      | Neo-Med             | 1              | Brick           | Low             |
| PF.M07.S1443                                             | 329            | Brookwood Cir      | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1469                                             | 401            | Brookwood Dr       | Building        | c 1966      | Domestic-single      | Second Empire       | 1              | Brick           | Medium          |
| PF.M07.S1468                                             | 407            | Brookwood Dr       | Building        | c 1968      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M07.S1461                                             | 3800           | Brookwood Dr       | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1460                                             | 3801           | Brookwood Dr       | Building        | c 1970      | Domestic-single      | Tudor Revival       | 1              | Brick           | Low             |
| PF.M07.S1463                                             | 3806           | Brookwood Dr       | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1459                                             | 3807           | Brookwood Dr       | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1463                                             | 3812           | Brookwood Dr       | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1458                                             | 3813           | Brookwood Dr       | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1464                                             | 3818           | Brookwood Dr       | Building        | c 1969      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M07.S1457                                             | 3819           | Brookwood Dr       | Building        | c 1969      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M07.S1465                                             | 3900           | Brookwood Dr       | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1456                                             | 3901           | Brookwood Dr       | Building        | c 1969      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1466                                             | 3906           | Brookwood Dr       | Building        | c 1965      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1467                                             | 3912           | Brookwood Dr       | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1455                                             | 3913           | Brookwood Dr       | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M02.S0422                                             | 2601           | Cameron Av         | Building        | c 1952      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0423                                             | 2607           | Cameron Av         | Building        | c 1952      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M02.S0424                                             | 2615           | Cameron Av         | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M02.S0421                                             | 2616           | Cameron Av         | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0425                                             | 2619           | Cameron Av         | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M02.S0426                                             | 2623           | Cameron Av         | Building        | c 1953      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0420                                             | 2624           | Cameron Av         | Building        | 1953        | Domestic-single      | Post-war Modern     | 1              | Brick           | High            |
| PF.M02.S0413                                             | 2730           | Cameron Av         | Building        | 1951        | Domestic-single      | Post-war Modern     | 1              | Wood            | High            |
| PF.M02.S0414                                             | 2733           | Cameron Av         | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M02.S0412                                             | 2738           | Cameron Av         | Building        | c 1967      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0698                                             | 2817           | Cameron Av         | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0699                                             | 2818           | Cameron Av         | Building        | 1951        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M04.S0700                                             | 2830           | Cameron Av         | Building        | 1952        | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | High            |
| PF.M04.S0701                                             | 2900           | Cameron Av         | Building        | c 1951      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0704                                             | 3000           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0702                                             | 3001           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0705                                             | 3002           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0721                                             | 3005           | Cameron Av         | Building        | c 1968      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0706                                             | 3008           | Cameron Av         | Building        | c 1962      | Domestic-single      | ER (Tahitian)       | 1              | Brick           | Medium          |
| PF.M04.S0720                                             | 3015           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival         | 1              | Brick           | Medium          |
| PF.M04.S0707                                             | 3016           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0710                                             | 3100 blk       | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Wood            | Medium          |
| PF.M04.S0719                                             | 3101           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0708                                             | 3104           | Cameron Av         | Building        | c 1962      | Domestic-single      | Greek Rev/Ranch     | 1              | Brick           | Medium          |
| PF.M04.S0718                                             | 3107           | Cameron Av         | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0709                                             | 3110           | Cameron Av         | Building        | c 1962      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0717                                             | 3115           | Cameron Av         | Building        | c 1962      | Domestic-single      | Ranch/Tudor Rev     | 1              | Brick           | Medium          |
| PF.M04.S0716                                             | 3121           | Cameron Av         | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0711                                             | 3122           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0712                                             | 3200           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0715                                             | 3207           | Cameron Av         | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0713                                             | 3208           | Cameron Av         | Building        | c 1962      | Domestic-single      | Storybook Ranch     | 1              | Brick           | Medium          |
| PF.M04.S0714                                             | 3216           | Cameron Av         | Building        | c 1967      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M06.S1024                                             | 3300           | Cameron Av         | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S1053                                             | 3301           | Cameron Av         | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S1025                                             | 3304           | Cameron Av         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S1052                                             | 3307           | Cameron Av         | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M06.S1026                                             | 3310           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1051                                             | 3313           | Cameron Av         | Building        | c 1970      | Domestic-single      | FCR/Ranch           | 1              | Brick           | Low             |
| PF.M06.S1027                                             | 3316           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1050                                             | 3319           | Cameron Av         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1028                                             | 3322           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1.5            | Brick           | Medium          |
| PF.M06.S1029                                             | 3328           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S1049                                             | 3331           | Cameron Av         | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1.5            | Brick           | Low             |
| PF.M06.S1736                                             | 3331           | Cameron Av         | Structure       | c 1964      | Infrastructure       | No style            | None           | Stone           | Medium          |
| PF.M06.S1030                                             | 3334           | Cameron Av         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1048                                             | 3337           | Cameron Av         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1.5            | Brick           | Low             |
| PF.M06.S1031                                             | 3338           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1.5            | Brick           | Low             |
| PF.M06.S1047                                             | 3401           | Cameron Av         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1032                                             | 3404           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1046                                             | 3407           | Cameron Av         | Building        | c 1963      | Domestic-single      | Tudor Rev/Ranch     | 1              | Brick           | Medium          |
| PF.M06.S1033                                             | 3410           | Cameron Av         | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1045                                             | 3411           | Cameron Av         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S1034                                             | 3416           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1044                                             | 3417           | Cameron Av         | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S1035                                             | 3506           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1043                                             | 3511           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M06.S1036                                             | 3512           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1042                                             | 3517           | Cameron Av         | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S1037                                             | 3518           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1041                                             | 3523           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S1038                                             | 3524           | Cameron Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S1040                                             | 3529           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1039                                             | 3530           | Cameron Av         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1642                                             | 3601           | Cameron Av         | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1643                                             | 3602           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1644                                             | 3606           | Cameron Av         | Building        | c 1965      | Domestic-single      | FCR/Ranch           | 1              | Brick           | Medium          |
| PF.M08.S1641                                             | 3607           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1645                                             | 3614           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1640                                             | 3615           | Cameron Av         | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1646                                             | 3622           | Cameron Av         | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1639                                             | 3623           | Cameron Av         | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1647                                             | 3628           | Cameron Av         | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1638                                             | 3629           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1648                                             | 3700           | Cameron Av         | Building        | c 1967      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1637                                             | 3701           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/CR/TR         | 1              | Brick           | Low             |
| PF.M08.S1649                                             | 3706           | Cameron Av         | Building        | c 1967      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1636                                             | 3707           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Col Revival      | 1              | Brick           | Low             |
| PF.M08.S1650                                             | 3714           | Cameron Av         | Building        | c 1966      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Medium          |
| PF.M08.S1635                                             | 3715           | Cameron Av         | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1651                                             | 3722           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch/PW-Modern     | 1              | Brick           | Low             |
| PF.M08.S1634                                             | 3723           | Cameron Av         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1652                                             | 3728           | Cameron Av         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1633                                             | 3729           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1653                                             | 3800           | Cameron Av         | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1632                                             | 3801           | Cameron Av         | Building        | c 1968      | Domestic-single      | Ranch/Neo-Med       | 1              | Brick           | Low             |
| PF.M08.S1654                                             | 3806           | Cameron Av         | Building        | c 1969      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1631                                             | 3807           | Cameron Av         | Building        | c 1964      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1655                                             | 3814           | Cameron Av         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1630                                             | 3815           | Cameron Av         | Building        | c 1966      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M08.S1656                                             | 3820           | Cameron Av         | Building        | c 1965      | Domestic-single      | Neo-Med             | 1              | Brick           | Medium          |
| PF.M08.S1657                                             | 3900           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1658                                             | 3906           | Cameron Av         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1629                                             | 3911           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1659                                             | 3912           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Wood            | Low             |
| PF.M08.S1628                                             | 3917           | Cameron Av         | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1660                                             | 3918           | Cameron Av         | Building        | c 1970      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M02.S0379                                             | 1128           | Cardwell Ln        | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M02.S0380                                             | 1301           | Cardwell Ln        | Building        | c 1953      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M02.S0378                                             | 1302           | Cardwell Ln        | Building        | c 1930      | Domestic-single      | No style          | 1              | Wood            | Medium          |
| PF.M02.S0377                                             | 1304           | Cardwell Ln        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0381                                             | 1305           | Cardwell Ln        | Building        | c 1963      | Domestic-single      | No style          | 1              | Vinyl           | Low             |
| PF.M02.S0376                                             | 1306           | Cardwell Ln        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0375                                             | 1308           | Cardwell Ln        | Building        | c 1940      | Domestic-single      | No style          | 1              | Wood            | Medium          |
| PF.M08.S1580                                             | 4100 blk       | Chester Dr         | Structure       | c 1964      | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M08.S1576                                             | 4101           | Chester Dr         | Building        | c 1970      | Domestic-single      | Ranch/Craftsman   | 1              | Brick           | Low             |
| PF.M08.S1577                                             | 4102           | Chester Dr         | Building        | c 1969      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M08.S1578                                             | 4106           | Chester Dr         | Building        | c 1965      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M08.S1575                                             | 4107           | Chester Dr         | Building        | c 1969      | Domestic-single      | Neo-Mediterranean | 1              | Brick           | Low             |
| PF.M08.S1574                                             | 4115           | Chester Dr         | Building        | c 1969      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M08.S1579                                             | 4116           | Chester Dr         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M03.S0454                                             | 600            | Clyde Dr           | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0453                                             | 608            | Clyde Dr           | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0452                                             | 614            | Clyde Dr           | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0451                                             | 620            | Clyde Dr           | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0450                                             | 626            | Clyde Dr           | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0449                                             | 632            | Clyde Dr           | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0448                                             | 914            | Clyde Dr           | Building        | c 1965      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0634                                             | 1002           | Clyde Dr           | Building        | c 1970      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0650                                             | 1003           | Clyde Dr           | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M04.S0635                                             | 1010           | Clyde Dr           | Building        | c 1963      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M04.S0649                                             | 1011           | Clyde Dr           | Building        | c 1961      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0648                                             | 1017           | Clyde Dr           | Building        | c 1961      | Domestic-single      | Colonial Revival  | 1.5            | Brick           | Low             |
| PF.M04.S0636                                             | 1018           | Clyde Dr           | Building        | c 1966      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0681                                             | 1024           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Ranch/PW Modern   | 1              | Brick           | Medium          |
| PF.M04.S0647                                             | 1025           | Clyde Dr           | Building        | c 1961      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0637                                             | 1100           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0646                                             | 1101           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0638                                             | 1106           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0645                                             | 1107           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0639                                             | 1112           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0644                                             | 1115           | Clyde Dr           | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0640                                             | 1118           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0641                                             | 1200           | Clyde Dr           | Building        | c 1961      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M04.S0642                                             | 1206           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0643                                             | 1212           | Clyde Dr           | Building        | c 1962      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Medium          |
| PF.M05.S1331                                             | 3100           | Colgate Av         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1332                                             | 3106           | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1333                                             | 3112           | Colgate Av         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1334                                             | 3120           | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1335                                             | 3126           | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1336                                             | 3132           | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1337                                             | 3138           | Colgate Av         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1338                                             | 3144           | Colgate Av         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1339                                             | 3200           | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1341                                             | 3200 blk       | Colgate Av         | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1340                                             | 3206           | Colgate Av         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1342                                             | 3228           | Colgate Av         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1356                                             | 3320           | Colgate Av         | Building        | c 1970      | Domestic-single      | French Col Revival  | 1              | Brick           | Low             |
| PF.M05.S1430                                             | 3400 blk       | Colgate Av         | Structure       | c 1965      | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M05.S1429                                             | 3401           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1428                                             | 3405           | Colgate Av         | Building        | c 1969      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1402                                             | 3408           | Colgate Av         | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1427                                             | 3409           | Colgate Av         | Building        | c 1969      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1426                                             | 3413           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1425                                             | 3417           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1403                                             | 3418           | Colgate Av         | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1424                                             | 3423           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1404                                             | 3424           | Colgate Av         | Building        | c 1969      | Domestic-single      | Ranch/SB            | 1-1.5          | Brick           | Low             |
| PF.M05.S1405                                             | 3500           | Colgate Av         | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1423                                             | 3501           | Colgate Av         | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1406                                             | 3506           | Colgate Av         | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1422                                             | 3507           | Colgate Av         | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1407                                             | 3512           | Colgate Av         | Building        | c 1969      | Domestic-single      | Neo-Mediterranean   | 1              | Brick           | Low             |
| PF.M05.S1421                                             | 3513           | Colgate Av         | Building        | c 1967      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M05.S1408                                             | 3518           | Colgate Av         | Building        | c 1968      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1420                                             | 3519           | Colgate Av         | Building        | c 1966      | Domestic-single      | Ranch/Neo-Med       | 1              | Brick           | Medium          |
| PF.M05.S1409                                             | 3600           | Colgate Av         | Building        | c 1969      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1419                                             | 3601           | Colgate Av         | Building        | c 1966      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1410                                             | 3606           | Colgate Av         | Building        | c 1969      | Domestic-single      | PW Modern/Ranch     | 1              | Brick           | Low             |
| PF.M05.S1418                                             | 3607           | Colgate Av         | Building        | c 1967      | Domestic-single      | Fr/Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1411                                             | 3612           | Colgate Av         | Building        | c 1969      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M05.S1417                                             | 3613           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1412                                             | 3700           | Colgate Av         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1416                                             | 3705           | Colgate Av         | Building        | c 1966      | Domestic-single      | Ranch/SB            | 1              | Brick           | Medium          |
| PF.M05.S1413                                             | 3706           | Colgate Av         | Building        | c 1967      | Domestic-single      | Fr Col Rev/Ranch    | 1              | Brick           | Low             |
| PF.M05.S1414                                             | 3712           | Colgate Av         | Building        | c 1966      | Domestic-single      | Neo-Med/Ranch       | 1              | Brick           | Medium          |
| PF.M05.S1415                                             | 3713           | Colgate Av         | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1478                                             | 3700-3702      | Colony Park Dr     | Building        | c 1970      | Domestic-duplex      | Colonial Revival    | 2              | Brick           | Low             |
| PF.M07.S1479                                             | 3704-3706      | Colony Park Dr     | Building        | c 1969      | Domestic-duplex      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1480                                             | 3708-3710      | Colony Park Dr     | Building        | c 1969      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M07.S1477                                             | 3711-3713      | Colony Park Dr     | Building        | c 1968      | Domestic-duplex      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M07.S1481                                             | 3712-3714      | Colony Park Dr     | Building        | c 1968      | Domestic-single      | Second Empire       | 1.5            | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M07.S1482                                             | 3716-3718      | Colony Park Dr     | Building        | c 1969      | Domestic-duplex      | Colonial Revival   | 1.5            | Brick           | Low             |
| PF.M07.S1476                                             | 3717-3715      | Colony Park Dr     | Building        | c 1970      | Domestic-duplex      | French Col Revival | 1              | Brick           | Low             |
| PF.M07.S1483                                             | 3720-3722      | Colony Park Dr     | Building        | c 1970      | Domestic-duplex      | Colonial Revival   | 1              | Brick           | Low             |
| PF.M07.S1484                                             | 3724-3726      | Colony Park Dr     | Building        | c 1970      | Domestic-duplex      | French Col Revival | 1              | Brick           | Low             |
| PF.M07.S1485                                             | 3728-2730      | Colony Park Dr     | Building        | c 1969      | Domestic-duplex      | Col Rev/Tudor Rev  | 1              | Brick           | Low             |
| PF.M07.S1475                                             | 3729-3731      | Colony Park Dr     | Building        | c 1965      | Domestic-duplex      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M07.S1486                                             | 3732-3734      | Colony Park Dr     | Building        | c 1968      | Domestic-duplex      | Second Empire      | 1.5            | Brick           | Low             |
| PF.M07.S1487                                             | 3736-3738      | Colony Park Dr     | Building        | c 1969      | Domestic-duplex      | FCR/Neo-Med        | 1              | Brick           | Low             |
| PF.M05.S1384                                             | 500            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1392                                             | 500 blk        | Cornell Pl         | Structure       | c 1955      | Infrastructure       | No style           | None           | Conc            | Medium          |
| PF.M05.S1385                                             | 502            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1386                                             | 504            | Cornell Pl         | Building        | c 1957      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1387                                             | 506            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1388                                             | 508            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M05.S1389                                             | 510            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M05.S1390                                             | 512            | Cornell Pl         | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1391                                             | 514            | Cornell Pl         | Building        | c 1955      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M03.S0511                                             | 2717           | Crestview Av       | Building        | c 1949      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0519                                             | 2722           | Crestview Av       | Building        | c 1948      | Domestic-single      | Colonial Revival   | 1              | Wood            | Low             |
| PF.M03.S0518                                             | 2724           | Crestview Av       | Building        | c 1948      | Domestic-single      | Colonial Revival   | 1              | Asbes           | Low             |
| PF.M03.S0512                                             | 2725           | Crestview Av       | Building        | c 1961      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0517                                             | 2734           | Crestview Av       | Building        | c 1948      | Domestic-single      | No style           | 1              | Vinyl           | Low             |
| PF.M03.S0513                                             | 2735           | Crestview Av       | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M03.S0516                                             | 2738           | Crestview Av       | Building        | c 1948      | Domestic-single      | Col Revival/Ranch  | 1              | Asbes           | Low             |
| PF.M03.S0515                                             | 2742           | Crestview Av       | Building        | c 1949      | Domestic-single      | Colonial Revival   | 1              | Brick           | Low             |
| PF.M03.S0514                                             | 2743           | Crestview Av       | Building        | c 1953      | Domestic-single      | Colonial Revival   | 1              | Brick           | Low             |
| PF.M03.S0520                                             | 2833           | Crestview Av       | Building        | c 1960      | Domestic-single      | Ranch              | 1              | Wood            | Low             |
| PF.M03.S0521                                             | 2901           | Crestview Av       | Building        | c 1963      | Domestic-single      | Ranch              | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M03.S0537                                             | 2912           | Crestview Av       | Building        | c 1950      | Domestic-single      | No style          | 1              | Wood            | Low             |
| PF.M03.S0522                                             | 2913           | Crestview Av       | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Wood            | Low             |
| PF.M03.S0536                                             | 2914           | Crestview Av       | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0535                                             | 2916           | Crestview Av       | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0523                                             | 2917           | Crestview Av       | Building        | c 1940      | Domestic-single      | No style          | 1              | Vinyl           | Low             |
| PF.M03.S0524                                             | 2925           | Crestview Av       | Building        | c 1970      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M03.S0534                                             | 2926           | Crestview Av       | Building        | c 1949      | Domestic-single      | No style          | 1              | Vinyl           | Low             |
| PF.M03.S0525                                             | 2929           | Crestview Av       | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Vinyl           | Low             |
| PF.M03.S0533                                             | 2930           | Crestview Av       | Building        | c 1940      | Domestic-single      | No style          | 1              | Asbes           | Low             |
| PF.M03.S0529                                             | 3000 blk       | Crestview Av       | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0526                                             | 3003           | Crestview Av       | Building        | c 1949      | Domestic-single      | Col Revival/Ranch | 1              | Vinyl           | Low             |
| PF.M03.S0532                                             | 3004           | Crestview Av       | Building        | c 1939      | Domestic-single      | Min Traditional   | 1              | Brick           | Low             |
| PF.M03.S0527                                             | 3007           | Crestview Av       | Building        | c 1949      | Domestic-single      | Ranch             | 1              | Vinyl           | Low             |
| PF.M03.S0531                                             | 3008           | Crestview Av       | Building        | c 1950      | Domestic-single      | Ranch             | 1              | Vinyl           | Low             |
| PF.M03.S0528                                             | 3011           | Crestview Av       | Building        | c 1968      | Domestic-single      | Col Revival/Ranch | 1              | Wood            | Low             |
| PF.M03.S0530                                             | 3014           | Crestview Av       | Building        | c 1949      | Domestic-single      | No style          | 1              | Asbes           | Low             |
| PF.M02.S0409                                             | 2745           | Curtis Dr          | Building        | c 1950      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M04.S0764                                             | 2817           | Curtis Dr          | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M04.S0763                                             | 2827           | Curtis Dr          | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0742                                             | 2828           | Curtis Dr          | Building        | 1953        | Domestic-single      | Ranch/FCR         | 1              | Brick           | High            |
| PF.M04.S0743                                             | 2830           | Curtis Dr          | Building        | c 1951      | Domestic-single      | No style          | 1              | Brick           | Low             |
| PF.M04.S0744                                             | 2832           | Curtis Dr          | Building        | c 1952      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M04.S0745                                             | 2834           | Curtis Dr          | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0762                                             | 2839           | Curtis Dr          | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M04.S0761                                             | 2907           | Curtis Dr          | Building        | 1952        | Domestic-single      | PW Mod/CR/Ranch   | 1              | Brick           | High            |
| PF.M04.S0760                                             | 2917           | Curtis Dr          | Building        | 1952        | Domestic-single      | Col Revival/Ranch | 1              | Brick           | High            |
| PF.M04.S0759                                             | 2925           | Curtis Dr          | Building        | c 1961      | Domestic-single      | Ranch/PW Modern   | 1              | Brick           | Low             |
| PF.M04.S0746                                             | 2926           | Curtis Dr          | Building        | c 1955      | Domestic-single      | PW Modern/Ranch   | 1 to 2         | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0747                                             | 2932           | Curtis Dr          | Building        | c 1953      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0758                                             | 3025           | Curtis Dr          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0747                                             | 3101           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0748                                             | 3110           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Col Rev/Min Trad    | 1              | Brick           | Medium          |
| PF.M04.S0756                                             | 3113           | Curtis Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0749                                             | 3116           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0755                                             | 3119           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0750                                             | 3126           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0754                                             | 3201           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Masonry         | Low             |
| PF.M04.S0753                                             | 3207           | Curtis Dr          | Building        | c 1954      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0751                                             | 3208           | Curtis Dr          | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0752                                             | 3215           | Curtis Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0927                                             | 3240           | Curtis Dr          | Building        | c 1958      | Domestic-single      | No style            | 1 to 2         | Brick           | Low             |
| PF.M06.S0928                                             | 3300           | Curtis Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1374                                             | 311            | Dartmouth Dr       | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M05.S1357                                             | 312            | Dartmouth Dr       | Building        | c 1969      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1373                                             | 319            | Dartmouth Dr       | Building        | c 1958      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1358                                             | 320            | Dartmouth Dr       | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1372                                             | 327            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1359                                             | 328            | Dartmouth Dr       | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1360                                             | 400            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1371                                             | 401            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1361                                             | 408            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1362                                             | 416            | Dartmouth Dr       | Building        | c 1957      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1370                                             | 421            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M05.S1369                                             | 501            | Dartmouth Dr       | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1368                                             | 507            | Dartmouth Dr       | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1363                                             | 510            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1367                                             | 515            | Dartmouth Dr       | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1364                                             | 516            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1365                                             | 522            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1366                                             | 523            | Dartmouth Dr       | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M04.S1738                                             | 1502           | DeCharles St       | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S0942                                             | 1503           | DeCharles St       | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0943                                             | 1527           | DeCharles St       | Building        | 1964        | Domestic-single      | Colonial Revival    | 1              | Brick           | High            |
| PF.M06.S0944                                             | 1601           | DeCharles St       | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0829                                             | 1714           | DeCharles St       | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0898                                             | 1725           | DeCharles St       | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0830                                             | 1800           | DeCharles St       | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0831                                             | 1800 blk       | DeCharles St       | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0899                                             | 1805           | DeCharles St       | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0832                                             | 1812           | DeCharles St       | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0900                                             | 1815           | DeCharles St       | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0686                                             | 3006           | DeCharles St       | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0687                                             | 3014           | DeCharles St       | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0688                                             | 3100           | DeCharles St       | Building        | c 1961      | Domestic-single      | Col/Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0697                                             | 3101           | DeCharles St       | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0696                                             | 3107           | DeCharles St       | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0689                                             | 3108           | DeCharles St       | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0690                                             | 3116           | DeCharles St       | Building        | c 1961      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0691                                             | 3122           | DeCharles St       | Building        | c 1961      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0692                                             | 3200           | DeCharles St       | Building        | c 1963      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0695                                             | 3203           | DeCharles St       | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0694                                             | 3213           | DeCharles St       | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0693                                             | 3223           | DeCharles St       | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0822                                             | 1505           | Dennis Dr          | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0820                                             | 1506           | Dennis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0819                                             | 1516           | Dennis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0821                                             | 1602           | Dennis Dr          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M04.S0828                                             | 1607           | Dennis Dr          | Building        | c 1953      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0827                                             | 1615           | Dennis Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0823                                             | 1618           | Dennis Dr          | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0826                                             | 1623           | Dennis Dr          | Building        | c 1954      | Domestic-single      | Post-war Modern   | 1              | Brick           | Low             |
| PF.M04.S0824                                             | 1626           | Dennis Dr          | Building        | 1954        | Domestic-single      | Post-war Modern   | 1              | Brick           | High            |
| PF.M04.S0845                                             | 2811           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0844                                             | 2812           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0843                                             | 2820           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0846                                             | 2821           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0842                                             | 2900           | Dinah Ln           | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0847                                             | 2901           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0841                                             | 2906           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0848                                             | 2907           | Dinah Ln           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0840                                             | 2914           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0849                                             | 2915           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0850                                             | 2921           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0839                                             | 2922           | Dinah Ln           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0838                                             | 2928           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0851                                             | 2929           | Dinah Ln           | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0837                                             | 2932           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0852                                             | 2933           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0836                                             | 2938           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0835                                             | 3000 blk       | Dinah Ln           | Structure       | c 1953      | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M04.S0853                                             | 3007           | Dinah Ln           | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M04.S0854                                             | 3117           | Dinah Ln           | Building        | 1955        | Domestic-single      | Ranch/Col Revival | 1              | Brick           | High            |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0834                                             | 3200           | Dinah Ln           | Building        | 1956        | Domestic-single      | Colonial Revival  | 1              | Brick           | High            |
| PF.M04.S0833                                             | 3200 blk       | Dinah Ln           | Structure       | c 1955      | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M04.S0855                                             | 3203           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0856                                             | 3211           | Dinah Ln           | Building        | 1956        | Domestic-single      | PW Modern/Ranch   | 1              | Brick           | High            |
| PF.M06.S0901                                             | 3213           | Dinah Ln           | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0907                                             | 3236           | Dinah Ln           | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0906                                             | 3242           | Dinah Ln           | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0905                                             | 3312           | Dinah Ln           | Building        | 1959        | Domestic-single      | Colonial Revival  | 1              | Brick           | High            |
| PF.M06.S0904                                             | 3322           | Dinah Ln           | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0902                                             | 3331           | Dinah Ln           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0903                                             | 3336           | Dinah Ln           | Building        | 1958        | Domestic-single      | Ranch/Col Revival | 1              | Brick           | High            |
| PF.M01.S0001                                             | 2400 blk       | Donnybrook Av      | Site            | c 1916      | Funerary-cemetery    | No style          | None           | Stone           | Medium          |
| PF.M1A.S0036                                             | 2602           | Donnybrook Av      | Building        | c 1952      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M03.S0269                                             | 2700 blk       | Donnybrook Av      | Building        | c 1940      | Domestic-single      | Tudor Rev/Col Rev | 1              | Stone           | Medium          |
| PF.M03.S0268                                             | 2712           | Donnybrook Av      | Building        | c 1910      | Domestic-single      | Folk Victorian    | 1              | Wood            | Medium          |
| PF.M03.S0267                                             | 2722           | Donnybrook Av      | Building        | c 1939      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M03.S0270                                             | 2727           | Donnybrook Av      | Building        | c 1945      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Medium          |
| PF.M03.S0266                                             | 2732           | Donnybrook Av      | Building        | c 1910      | Domestic-single      | No style          | 1              | Wood            | Low             |
| PF.M03.S0271                                             | 2737           | Donnybrook Av      | Building        | c 1940      | Domestic-single      | Colonial Revival  | 2              | Wood            | High            |
| PF.M03.S0272                                             | 2800           | Donnybrook Av      | Building        | c 1910      | Domestic-single      | No style          | 1              | Wood            | Medium          |
| PF.M03.S0558                                             | 2800 blk       | Donnybrook Av      | Building        | c 1965      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0274                                             | 2800 blk       | Donnybrook Av      | Building        | c 1950      | Unknown              | No style          | 1              | Wood            | Low             |
| PF.M03.S0273                                             | 2808           | Donnybrook Av      | Building        | c 1934      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M03.S0557                                             | 2824           | Donnybrook Av      | Building        | c 1910      | Domestic-single      | No style          | 1.5            | Wood            | Low             |
| PF.M03.S0556                                             | 2829           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0555                                             | 2832           | Donnybrook Av      | Building        | c 1949      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M03.S0559                                             | 2835           | Donnybrook Av      | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M03.S0554                                             | 2900           | Donnybrook Av      | Building        | c 1937      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M03.S0560                                             | 2903           | Donnybrook Av      | Building        | c 1933      | Domestic-single      | Craftsman         | 1              | Vinyl           | Medium          |
| PF.M03.S0553                                             | 2906           | Donnybrook Av      | Building        | c 1951      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0552                                             | 2914           | Donnybrook Av      | Building        | c 1923      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0551                                             | 2920           | Donnybrook Av      | Building        | c 1949      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M03.S0550                                             | 2930           | Donnybrook Av      | Building        | c 1947      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |
| PF.M03.S0549                                             | 2934           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M03.S0548                                             | 2938           | Donnybrook Av      | Building        | c 1948      | Domestic-single      | No style          | 1              | Vinyl           | Low             |
| PF.M05.S1279                                             | 3100           | Donnybrook Av      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M05.S1285                                             | 3100 blk       | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1278                                             | 3101           | Donnybrook Av      | Building        | c 1958      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Medium          |
| PF.M05.S1280                                             | 3106           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1277                                             | 3107           | Donnybrook Av      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1281                                             | 3112           | Donnybrook Av      | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1276                                             | 3115           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1282                                             | 3120           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1275                                             | 3121           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1283                                             | 3124           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch/FCR         | 1              | Brick           | Medium          |
| PF.M05.S1274                                             | 3125           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1284                                             | 3128           | Donnybrook Av      | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1273                                             | 3131           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1272                                             | 3137           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1286                                             | 3142           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1271                                             | 3143           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1290                                             | 3200 blk       | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1270                                             | 3201           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1287                                             | 3202           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1269                                             | 3205           | Donnybrook Av      | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1288                                             | 3210           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1289                                             | 3216           | Donnybrook Av      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1268                                             | 3225           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1291                                             | 3228           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1267                                             | 3229           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Unknown           | 1              | Brick           | Low             |
| PF.M05.S1292                                             | 3236           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1355                                             | 3300           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1293                                             | 3312           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | No style          | 1              | Brick           | Low             |
| PF.M05.S1266                                             | 3315           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1265                                             | 3321           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1294                                             | 3322           | Donnybrook Av      | Building        | c 1955      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Medium          |
| PF.M07.S1436                                             | 3800           | Donnybrook Av      | Building        | c 1966      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M07.S1437                                             | 3806           | Donnybrook Av      | Building        | c 1968      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M07.S1438                                             | 3814           | Donnybrook Av      | Building        | c 1969      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M07.S1439                                             | 3820           | Donnybrook Av      | Building        | c 1969      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M07.S1440                                             | 3900           | Donnybrook Av      | Building        | c 1968      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Low             |
| PF.M07.S1441                                             | 3906           | Donnybrook Av      | Building        | c 1970      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Low             |
| PF.M07.S1442                                             | 3912           | Donnybrook Av      | Building        | c 1965      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M07.S1742                                             | 4000 blk       | Donnybrook Av      | Structure       | c 1960s     | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M07.S1734                                             | 4000 blk       | Donnybrook Av      | Structure       | c 1960s     | Infrastructure       | No style          | None           | Earth           | Medium          |
| PF.M03.S0265                                             | 416            | Dulse St           | Building        | c 1955      | Domestic-single      | Ranch             | 1 to 2         | Brick           | Low             |
| PF.M03.S0429                                             | 509            | Dulse St           | Building        | c 1947      | Domestic-single      | Colonial Revival  | 2              | Asbes           | Medium          |
| PF.M03.S0264                                             | 614            | Dulse St           | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M03.S0263                                             | 620            | Dulse St           | Building        | c 1949      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0262                                             | 626            | Dulse St           | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0261                                             | 632            | Dulse St           | Building        | c 1945      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M03.S0260                                             | 638            | Dulse St           | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M03.S0259                                             | 708            | Dulse St           | Building        | c 1952      | Domestic-single      | Colonial Revival  | 1 to 2         | Brick           | Medium          |
| PF.M01.S0258                                             | 716            | Dulse St           | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0257                                             | 724            | Dulse St           | Building        | c 1949      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0256                                             | 730            | Dulse St           | Building        | c 1950      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0255                                             | 736            | Dulse St           | Building        | c 1950      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0254                                             | 802            | Dulse St           | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0428                                             | 815            | Dulse St           | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0361                                             | 816            | Dulse St           | Building        | c 1951      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0253                                             | 904            | Dulse St           | Building        | c 1955      | Domestic-single      | Post-war Modern     | 1              | Brick           | Medium          |
| PF.M01.S0252                                             | 918            | Dulse St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0427                                             | 919            | Dulse St           | Building        | c 1940      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0251                                             | 1002           | Dulse St           | Building        | 1955        | Domestic-single      | Fr Colonial Revival | 1.5            | Brick           | High            |
| PF.M02.S0250                                             | 1004           | Dulse St           | Building        | c 1952      | Domestic-vacant      | PWMod/Sp Ranch      | 1              | Brick           | Low             |
| PF.M02.S0419                                             | 1104           | Dulse St           | Building        | c 1952      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0623                                             | 1109           | Dulse St           | Building        | c 1951      | Domestic-single      | PW Modern/Ranch     | 1              | Brick           | Medium          |
| PF.M02.S0418                                             | 1116           | Dulse St           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0622                                             | 1123           | Dulse St           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M02.S0416                                             | 1206           | Dulse St           | Building        | 1960        | Domestic-single      | Colonial Revival    | 1              | Brick           | High            |
| PF.M04.S0621                                             | 1209           | Dulse St           | Building        | 1952        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M02.S0415                                             | 1216           | Dulse St           | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M02.S0411                                             | 1308           | Dulse St           | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0410                                             | 1318           | Dulse St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0620                                             | 1415           | Dulse St           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0619                                             | 1501           | Dulse St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0618                                             | 1513           | Dulse St           | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1696                                             | 1411           | Easy St            | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1687                                             | 1412           | Easy St            | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1688                                             | 1416           | Easy St            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1695                                             | 1419           | Easy St            | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1689                                             | 1422           | Easy St            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1694                                             | 1425           | Easy St            | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1690                                             | 1428           | Easy St            | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1693                                             | 1501           | Easy St            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1691                                             | 1502           | Easy St            | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1692                                             | 1508           | Easy St            | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M02.S0382                                             | 2517           | Fleishel Av        | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M02.S0383                                             | 2531           | Fleishel Av        | Building        | c 1940      | Domestic-single      | No style            | 1              | Brick           | Low             |
| PF.M04.S0672                                             | 2802           | Fry Av             | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0673                                             | 2816           | Fry Av             | Building        | 1951        | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M03.S0446                                             | 2817           | Fry Av             | Building        | 1954        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M04.S0674                                             | 2828           | Fry Av             | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M03.S0447                                             | 2927           | Fry Av             | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0675                                             | 3100           | Fry Av             | Building        | c 1961      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0676                                             | 3108           | Fry Av             | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Wood            | Medium          |
| PF.M04.S0677                                             | 3200           | Fry Av             | Building        | c 1961      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1136                                             | 3205           | Fry Av             | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1088                                             | 3214           | Fry Av             | Building        | c 1963      | Domestic-single      | FCR/Ranch           | 1              | Brick           | High            |
| PF.M05.S1135                                             | 3215           | Fry Av             | Building        | c 1970      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M06.S1089                                             | 3224           | Fry Av             | Building        | c 1964      | Domestic-single      | Ranch/Col           | 1              | Brick           | Medium          |
| PF.M05.S1134                                             | 3225           | Fry Av             | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1090                                             | 3234           | Fry Av             | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1133                                             | 3235           | Fry Av             | Building        | c 1962      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M06.S1094                                             | 3300 blk       | Fry Av             | Structure       | c 1960s     | Infrastructure       | No style            | None           | Stone           | Medium          |
| PF.M05.S1132                                             | 3305           | Fry Av             | Building        | 1963        | Domestic-single      | Post-war Modern     | 1              | Brick           | Medium          |
| PF.M06.S1091                                             | 3306           | Fry Av             | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1092                                             | 3316           | Fry Av             | Building        | 1964        | Domestic-single      | Colonial Revival    | 1.5            | Brick           | High            |
| PF.M05.S1131                                             | 3317           | Fry Av             | Building        | 1965        | Domestic-single      | Tudor Revival       | 1.5            | Brick           | High            |
| PF.M06.S1093                                             | 3326           | Fry Av             | Building        | c 1965      | Domestic-single      | Colonial Revival    | 1 to 2         | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1130                                             | 3327           | Fry Av             | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1129                                             | 3405           | Fry Av             | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M06.S1095                                             | 3406           | Fry Av             | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1128                                             | 3415           | Fry Av             | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1 to 2         | Brick           | Medium          |
| PF.M06.S1096                                             | 3416           | Fry Av             | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1127                                             | 3425           | Fry Av             | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1097                                             | 3506           | Fry Av             | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1744                                             | 3507           | Fry Av             | Building        | c 1970      | Domestic-single      | Colonial Revival    | 2              | Brick           | Low             |
| PF.M06.S1098                                             | 3512           | Fry Av             | Building        | c 1963      | Domestic-single      | Colonial Revival    | 2              | Brick           | Medium          |
| PF.M05.S1126                                             | 3519           | Fry Av             | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1 to 2         | Brick           | Medium          |
| PF.M06.S1099                                             | 3520           | Fry Av             | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M07.S1507                                             | 3701           | Fry Av             | Building        | c 1959      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1539                                             | 3714           | Fry Av             | Building        | c 1970      | Domestic-single      | Ranch               | 1              | Wood            | Low             |
| PF.M07.S1508                                             | 3715           | Fry Av             | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1540                                             | 3720           | Fry Av             | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M07.S1509                                             | 3721           | Fry Av             | Building        | 1962        | Domestic-single      | Colonial Revival    | 1              | Brick           | High            |
| PF.M07.S1510                                             | 3727           | Fry Av             | Building        | c 1958      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Medium          |
| PF.M08.S1541                                             | 3800           | Fry Av             | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1511                                             | 3801           | Fry Av             | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M07.S1512                                             | 3809           | Fry Av             | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1513                                             | 3819           | Fry Av             | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1542                                             | 3826           | Fry Av             | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M07.S1514                                             | 3827           | Fry Av             | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1543                                             | 3832           | Fry Av             | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M07.S1515                                             | 3835           | Fry Av             | Building        | c 1960      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1544                                             | 3838           | Fry Av             | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1545                                             | 3904           | Fry Av             | Building        | c 1960      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M07.S1516                                             | 3905           | Fry Av             | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1 to 2         | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1546                                             | 3912           | Fry Av             | Building        | c 1961      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1517                                             | 3913           | Fry Av             | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1547                                             | 3918           | Fry Av             | Building        | c 1962      | Domestic-single      | Greek Rev/Col Rev   | 1              | Brick           | Medium          |
| PF.M07.S1518                                             | 3919           | Fry Av             | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1519                                             | 3923           | Fry Av             | Building        | c 1963      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M07.S1520                                             | 4011           | Fry Av             | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Low             |
| PF.M07.S1521                                             | 4021           | Fry Av             | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1548                                             | 4100 blk       | Fry Av             | Building        | c 1969      | Domestic-single      | Neo-Med             | 1              | Brick           | Low             |
| PF.M07.S1522                                             | 4101           | Fry Av             | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1523                                             | 4111           | Fry Av             | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1454                                             | 300 blk        | Glen Cove Cir      | Structure       | c 1965      | Infrastructure       | No style            | None           | Conc            | Low             |
| PF.M07.S1452                                             | 322            | Glen Cove Cir      | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M07.S1451                                             | 325            | Glen Cove Cir      | Building        | c 1970      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1453                                             | 328            | Glen Cove Cir      | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1450                                             | 329            | Glen Cove Cir      | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S0993                                             | 1400 blk       | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0983                                             | 1408           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1 to 2         | Brick           | Low             |
| PF.M06.S0996                                             | 1409           | Glenrose St        | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0984                                             | 1414           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0995                                             | 1415           | Glenrose St        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0985                                             | 1420           | Glenrose St        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0994                                             | 1423           | Glenrose St        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0986                                             | 1428           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M06.S0992                                             | 1435           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0987                                             | 1500           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Low             |
| PF.M06.S0991                                             | 1505           | Glenrose St        | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0988                                             | 1506           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0990                                             | 1511           | Glenrose St        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0989                                             | 1512           | Glenrose St        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0083                                             | 400 blk        | Haden St           | Building        | c 1953      | Domestic-single      | No Style          | 1              | Wood            | Low             |
| PF.M01.S0089                                             | 401            | Haden St           | Building        | c 1951      | Domestic-single      | Min Traditional   | 1              | Wood            | Low             |
| PF.M01.S0080                                             | 402            | Haden St           | Building        | c 1946      | Domestic-single      | Min Traditional   | 1              | Asbestos        | Low             |
| PF.M01.S0088                                             | 407            | Haden St           | Building        | c 1946      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |
| PF.M01.S0081                                             | 408            | Haden St           | Building        | c 1949      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M01.S0087                                             | 411            | Haden St           | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M01.S0082                                             | 414            | Haden St           | Building        | c 1946      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |
| PF.M01.S0086                                             | 415            | Haden St           | Building        | c 1946      | Domestic-single      | Min Traditional   | 1              | Vinyl           | Low             |
| PF.M01.S0085                                             | 417            | Haden St           | Building        | c 1946      | Domestic-single      | No Style          | 1              | Vinyl           | Low             |
| PF.M01.S0084                                             | 421            | Haden St           | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M01.S0090                                             | 626            | Haden St           | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M01.S0098                                             | 627            | Haden St           | Building        | c 1950      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0091                                             | 632            | Haden St           | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0097                                             | 633            | Haden St           | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M01.S0094                                             | 700 blk        | Haden St           | Building        | c 1965      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0096                                             | 703            | Haden St           | Building        | c 1950      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M01.S0092                                             | 704            | Haden St           | Building        | c 1948      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M01.S0095                                             | 709            | Haden St           | Building        | c 1950      | Domestic-single      | No Style          | 2              | Wood            | Low             |
| PF.M01.S0093                                             | 710            | Haden St           | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0099                                             | 821            | Haden St           | Building        | c 1964      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0114                                             | 900            | Haden St           | Building        | c 1961      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0100                                             | 901            | Haden St           | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0113                                             | 902            | Haden St           | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0101                                             | 905            | Haden St           | Building        | c 1957      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0112                                             | 908            | Haden St           | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0102                                             | 909            | Haden St           | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0111                                             | 912            | Haden St           | Building        | c 1961      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0110                                             | 916            | Haden St           | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0103                                             | 923            | Haden St           | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S0109                                             | 1000           | Haden St           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0104                                             | 1001           | Haden St           | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0108                                             | 1008           | Haden St           | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M01.S0105                                             | 1009           | Haden St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0107                                             | 1012           | Haden St           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0106                                             | 1015           | Haden St           | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0776                                             | 3017           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0765                                             | 3018           | Hallmark Pl        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M04.S0766                                             | 3102           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0775                                             | 3103           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0767                                             | 3110           | Hallmark Pl        | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M04.S0774                                             | 3111           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0768                                             | 3112           | Hallmark Pl        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0773                                             | 3127           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0769                                             | 3200           | Hallmark Pl        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S1739                                             | 3200 blk       | Hallmark Pl        | Structure       | c 1950s     | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M04.S0772                                             | 3205           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0770                                             | 3216           | Hallmark Pl        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M04.S0771                                             | 3217           | Hallmark Pl        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1607                                             | 1017           | Hansford Pl        | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1599                                             | 1018           | Hansford Pl        | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1606                                             | 1023           | Hansford Pl        | Building        | c 1963      | Domestic-single      | PW Modern (Shed)    | 1              | Brick           | Medium          |
| PF.M08.S1600                                             | 1024           | Hansford Pl        | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1601                                             | 1100           | Hansford Pl        | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1602                                             | 1106           | Hansford Pl        | Building        | 1960        | Domestic-single      | Post-war Modern     | 1              | Brick           | High            |
| PF.M08.S1605                                             | 1107           | Hansford Pl        | Building        | c 1967      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1603                                             | 1116           | Hansford Pl        | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1604                                             | 1117           | Hansford Pl        | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1069                                             | 1106           | Heines Dr          | Building        | c 1970      | Domestic-single      | Second Empire       | 2              | Brick           | Low             |
| PF.M06.S1074                                             | 3300 Blk       | Heines Dr          | Building        | c 1967      | Domestic-single      | Col Revival/FCR     | 1              | Brick           | Low             |
| PF.M06.S1070                                             | 3335           | Heines Dr          | Building        | c 1965      | Domestic-single      | FCR/Ranch           | 1.5            | Brick           | Medium          |
| PF.M06.S1075                                             | 3400           | Heines Dr          | Building        | c 1970      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M06.S1076                                             | 3406           | Heines Dr          | Building        | c 1967      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M06.S1071                                             | 3407           | Heines Dr          | Building        | c 1970      | Domestic-single      | Tudor Rev/Col Rev   | 1.5            | Brick           | Low             |
| PF.M06.S1072                                             | 3413           | Heines Dr          | Building        | c 1966      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1077                                             | 3416           | Heines Dr          | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Stone           | Medium          |
| PF.M06.S1073                                             | 3417           | Heines Dr          | Building        | c 1965      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M04.S0658                                             | 1002           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0671                                             | 1009           | Hudnall Dr         | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0659                                             | 1010           | Hudnall Dr         | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0670                                             | 1015           | Hudnall Dr         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0660                                             | 1018           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0669                                             | 1021           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0661                                             | 1024           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0668                                             | 1031           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0662                                             | 1104           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0667                                             | 1105           | Hudnall Dr         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0666                                             | 1111           | Hudnall Dr         | Building        | c 1960      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0663                                             | 1112           | Hudnall Dr         | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0665                                             | 1119           | Hudnall Dr         | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0664                                             | 1120           | Hudnall Dr         | Building        | c 1960      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0042                                             | 405            | Hudson St          | Building        | c 1948      | Domestic-single      | No style            | 1              | Asbes           | Low             |
| PF.M01.S0043                                             | 409            | Hudson St          | Building        | c 1946      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M01.S0076                                             | 410            | Hudson St          | Building        | c 1952      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0044                                             | 415            | Hudson St          | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M01.S0075                                             | 416            | Hudson St          | Building        | c 1952      | Domestic-single      | Min Traditional   | 1              | Brick           | Low             |
| PF.M01.S0074                                             | 420            | Hudson St          | Building        | 1955        | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0045                                             | 421            | Hudson St          | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M01.S0073                                             | 426            | Hudson St          | Building        | 1955        | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0046                                             | 427            | Hudson St          | Building        | 1955        | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0047                                             | 429            | Hudson St          | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0072                                             | 430            | Hudson St          | Building        | 1955        | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0048                                             | 435            | Hudson St          | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0070                                             | 600 blk        | Hudson St          | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0049                                             | 627            | Hudson St          | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0071                                             | 630            | Hudson St          | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0050                                             | 635            | Hudson St          | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0069                                             | 702            | Hudson St          | Building        | c 1949      | Domestic-single      | Min Trad/Col Rev  | 1              | Brick           | Low             |
| PF.M01.S0051                                             | 703            | Hudson St          | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0052                                             | 709            | Hudson St          | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0068                                             | 710            | Hudson St          | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0067                                             | 714            | Hudson St          | Building        | c 1961      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0066                                             | 800            | Hudson St          | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M02.S0065                                             | 900 blk        | Hudson St          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0053                                             | 901            | Hudson St          | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0054                                             | 907            | Hudson St          | Building        | c 1959      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0055                                             | 917            | Hudson St          | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0064                                             | 918            | Hudson St          | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0063                                             | 920            | Hudson St          | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0056                                             | 923            | Hudson St          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0057                                             | 1001           | Hudson St          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0058                                             | 1007           | Hudson St          | Building        | c 1965      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M02.S0062                                             | 1012           | Hudson St          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0059                                             | 1015           | Hudson St          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M02.S0061                                             | 1020           | Hudson St          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0060                                             | 1021           | Hudson St          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0417                                             | 2808           | Itten Dr           | Building        | c 1960      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0703                                             | 2900 blk       | Jan Av             | Structure       | c 1960      | Infrastructure       | No Style          | 1              | Brick           | High            |
| PF.M04.S1735                                             | 2900 blk       | Jan Av             | Structure       | c 1960      | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M04.S0722                                             | 2918           | Jan Av             | Building        | c 1965      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0723                                             | 3000           | Jan Av             | Building        | 1956        | Domestic-single      | Colonial Revival  | 1              | Brick           | High            |
| PF.M04.S0741                                             | 3001           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0740                                             | 3005           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/PW Modern   | 1              | Brick           | Medium          |
| PF.M04.S0777                                             | 3010           | Jan Av             | Building        | c 1957      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0739                                             | 3011           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0724                                             | 3016           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0738                                             | 3017           | Jan Av             | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0737                                             | 3023           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0725                                             | 3100           | Jan Av             | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0736                                             | 3107           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0726                                             | 3108           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0735                                             | 3115           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M04.S0727                                             | 3118           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1.5            | Brick           | Low             |
| PF.M04.S0734                                             | 3121           | Jan Av             | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0728                                             | 3126           | Jan Av             | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S1022                                             | 3200 blk       | Jan Av             | Building        | c 1954      | Domestic-vacant      | Ranch             | 1              | Brick           | Low             |
| PF.M04.S0733                                             | 3201           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M04.S0729                                             | 3204           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M04.S0732                                             | 3207           | Jan Av             | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M04.S0731                                             | 3217           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M04.S0730                                             | 3218           | Jan Av             | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S1023                                             | 3231           | Jan Av             | Building        | c 1955      | Domestic-vacant      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S1740                                             | 3232           | Jan Av             | Building        | c 1955      | Religious-church     | Post-war Modern   | 1              | Brick           | Medium          |
| PF.M06.S1021                                             | 3243           | Jan Av             | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1016                                             | 3300 blk       | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1020                                             | 3301           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S1019                                             | 3307           | Jan Av             | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S1018                                             | 3317           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S1017                                             | 3325           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1015                                             | 3333           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1014                                             | 3401           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1013                                             | 3411           | Jan Av             | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S1012                                             | 3417           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S1009                                             | 3500 blk       | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1011                                             | 3505           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1010                                             | 3511           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0982                                             | 3512           | Jan Av             | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S1008                                             | 3601           | Jan Av             | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0997                                             | 3606           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1007                                             | 3611           | Jan Av             | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1006                                             | 3617           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1674                                             | 3703           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1675                                             | 3704           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1673                                             | 3709           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M08.S1672                                             | 3715           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1671                                             | 3801           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1670                                             | 3805           | Jan Av             | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1669                                             | 3811           | Jan Av             | Building        | c 1955      | Domestic-single      | French Co Revival | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1676                                             | 3812           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1668                                             | 3817           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1661                                             | 3900 blk       | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M08.S1667                                             | 3903           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Syn             | Low             |
| PF.M08.S1677                                             | 3904           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/PW Modern    | 1              | Brick           | Medium          |
| PF.M08.S1666                                             | 3909           | Jan Av             | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1678                                             | 3912           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M08.S1665                                             | 3915           | Jan Av             | Building        | c 1956      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1679                                             | 3916           | Jan Av             | Building        | c 1958      | Domestic-single      | French Col Revival | 1              | Brick           | Medium          |
| PF.M08.S1664                                             | 3921           | Jan Av             | Building        | c 1956      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1680                                             | 3922           | Jan Av             | Building        | c 1957      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M08.S1663                                             | 3925           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1681                                             | 3926           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M08.S1662                                             | 3929           | Jan Av             | Building        | c 1958      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M08.S1682                                             | 3932           | Jan Av             | Building        | c 1958      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0362                                             | 2704           | Keaton Av          | Building        | c 1951      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M03.S0460                                             | 2806           | Keaton Av          | Building        | 1949        | Domestic-single      | PW Mod/Internat'l  | 1              | Brick           | High            |
| PF.M03.S0461                                             | 2811           | Keaton Av          | Building        | c 1950      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M03.S0462                                             | 2815           | Keaton Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0463                                             | 2911           | Keaton Av          | Building        | c 1963      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0459                                             | 2920           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M03.S0464                                             | 2921           | Keaton Av          | Building        | c 1960      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0458                                             | 2926           | Keaton Av          | Building        | c 1961      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0465                                             | 2927           | Keaton Av          | Building        | c 1960      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0466                                             | 2933           | Keaton Av          | Building        | c 1961      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M03.S0457                                             | 2934           | Keaton Av          | Building        | c 1961      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M05.S1177                                             | 3201           | Keaton Av          | Building        | c 1965      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M05.S1137                                             | 3204           | Keaton Av          | Building        | c 1968      | Domestic-single      | Ranch              | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1176                                             | 3207           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M05.S1138                                             | 3210           | Keaton Av          | Building        | c 1968      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1175                                             | 3211           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1139                                             | 3216           | Keaton Av          | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1174                                             | 3219           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1140                                             | 3222           | Keaton Av          | Building        | c 1968      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1173                                             | 3225           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1141                                             | 3228           | Keaton Av          | Building        | c 1968      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1172                                             | 3231           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1142                                             | 3234           | Keaton Av          | Building        | c 1959      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M05.S1171                                             | 3237           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1143                                             | 3300           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch/SB          | 1              | Brick           | Low             |
| PF.M05.S1167                                             | 3300 blk       | Keaton Av          | Building        | c 1957      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M05.S1170                                             | 3301           | Keaton Av          | Building        | c 1959      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M05.S1144                                             | 3306           | Keaton Av          | Building        | c 1959      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Medium          |
| PF.M05.S1169                                             | 3307           | Keaton Av          | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Wood            | Medium          |
| PF.M05.S1145                                             | 3314           | Keaton Av          | Building        | c 1965      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1168                                             | 3315           | Keaton Av          | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1146                                             | 3318           | Keaton Av          | Building        | c 1965      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1166                                             | 3323           | Keaton Av          | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1147                                             | 3324           | Keaton Av          | Building        | c 1955      | Domestic-single      | No style          | 1              | Brick           | Low             |
| PF.M05.S1148                                             | 3330           | Keaton Av          | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1149                                             | 3404           | Keaton Av          | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1150                                             | 3414           | Keaton Av          | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M05.S1165                                             | 3415           | Keaton Av          | Building        | c 1956      | Domestic-vacant      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M05.S1164                                             | 3423           | Keaton Av          | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1151                                             | 3428           | Keaton Av          | Building        | 1956        | Domestic-single      | PW Modern/Ranch   | 1              | Brick           | High            |
| PF.M05.S1163                                             | 3429           | Keaton Av          | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1152                                             | 3500           | Keaton Av          | Building        | c 1954      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1162                                             | 3503           | Keaton Av          | Building        | c 1956      | Domestic-single      | No style            | 1              | Brick           | Low             |
| PF.M05.S1153                                             | 3508           | Keaton Av          | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1061                                             | 3511           | Keaton Av          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1154                                             | 3514           | Keaton Av          | Building        | c 1970      | Domestic-single      | Col Revival         | 1              | Brick           | Low             |
| PF.M05.S1160                                             | 3519           | Keaton Av          | Building        | c 1957      | Domestic-single      | Col Revival         | 1              | Brick           | Low             |
| PF.M05.S1155                                             | 3522           | Keaton Av          | Building        | c 1958      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M05.S1159                                             | 3525           | Keaton Av          | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1158                                             | 3527           | Keaton Av          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1156                                             | 3528           | Keaton Av          | Building        | c 1957      | Domestic-single      | Post-war Modern     | 1              | Brick           | Low             |
| PF.M05.S1157                                             | 3529           | Keaton Av          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0374                                             | 1301           | Lamar St           | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M02.S0373                                             | 1303           | Lamar St           | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M02.S0372                                             | 1307           | Lamar St           | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M02.S0371                                             | 1309           | Lamar St           | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M02.S0370                                             | 1323           | Lamar St           | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M02.S0369                                             | 1327           | Lamar St           | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S0170                                             | 801            | Leard Ln           | Building        | c 1940      | Domestic-single      | Neo-Classical       | 1.5            | Wood            | Medium          |
| PF.M01.S0169                                             | 806            | Leard Ln           | Building        | c 1940      | Domestic-single      | Colonial Revival    | 1              | Asbes           | Medium          |
| PF.M01.S0168                                             | 810            | Leard Ln           | Building        | c 1950      | Domestic-single      | No style            | 1              | Asbes           | Low             |
| PF.M05.S1375                                             | 500            | Lehigh Pl          | Building        | c 1958      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |
| PF.M05.S1380                                             | 500 blk        | Lehigh Pl          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1376                                             | 504            | Lehigh Pl          | Building        | c 1955      | Domestic-single      | Post-war Modern     | 1              | Brick           | Medium          |
| PF.M05.S1377                                             | 508            | Lehigh Pl          | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Wood            | Medium          |
| PF.M05.S1383                                             | 509            | Lehigh Pl          | Building        | c 1955      | Domestic-single      | Ranch/CR/PW Mod     | 1              | Brick           | Medium          |
| PF.M05.S1378                                             | 512            | Lehigh Pl          | Building        | c 1955      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1379                                             | 516            | Lehigh Pl          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1381                                             | 519            | Lehigh Pl          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1382                                             | 515            | Lehigh St          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0025                                             | 402            | Loftin St          | Building        | c 1943      | Domestic-single      | Min Traditional   | 1              | Asbes           | Low             |
| PF.M01.S0129                                             | 408            | Loftin St          | Building        | c 1946      | Domestic-single      | Greek Revival     | 1              | Vinyl           | Low             |
| PF.M01.S0128                                             | 414            | Loftin St          | Building        | c 1941      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M01.S0130                                             | 415            | Loftin St          | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Asbes           | Low             |
| PF.M01.S0131                                             | 423            | Loftin St          | Building        | 1951        | Domestic-single      | Min Trad/Col Rev  | 1              | Wood            | Medium          |
| PF.M01.S0134                                             | 500 blk        | Loftin St          | Structure       | Unknown     | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M01.S0135                                             | 500 blk        | Loftin St          | Structure       | Unknown     | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M01.S0132                                             | 507            | Loftin St          | Building        | c 1956      | Domestic-single      | No style          | 1              | Brick           | Low             |
| PF.M01.S0133                                             | 509            | Loftin St          | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0125                                             | 625            | Loftin St          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0124                                             | 626            | Loftin St          | Building        | c 1951      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0123                                             | 630            | Loftin St          | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0126                                             | 635            | Loftin St          | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0122                                             | 700            | Loftin St          | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0127                                             | 703            | Loftin St          | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0121                                             | 708            | Loftin St          | Building        | c 1949      | Domestic-single      | Ranch             | 1              | Wood            | Low             |
| PF.M01.S0115                                             | 832            | Loftin St          | Building        | c 1968      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0116                                             | 900            | Loftin St          | Building        | c 1962      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0117                                             | 908            | Loftin St          | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M01.S0118                                             | 914            | Loftin St          | Building        | c 1962      | Domestic-single      | Post-war Modern   | 1              | Brick           | Low             |
| PF.M01.S0119                                             | 920            | Loftin St          | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M01.S0120                                             | 928            | Loftin St          | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Wood            | Medium          |
| PF.M07.S1524                                             | 426            | Loop 323 ESE       | Building        | c 1960s     | Commerce/Trade       | No style          | 1              | Brick           | Low             |
| PF.M07.S1743                                             | 600 blk        | Loop 323 ESE       | Structure       | c 1960s     | Infrastructure       | No style          | None           | Conc            | Low             |
| PF.M08.S1538                                             | 1000 blk       | Loop 323 ESE       | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1683                                             | 1320           | Loop 323 ESE       | Building        | c 1964      | Commerce/Trade       | Ranch/Col Revival | 1              | Brick           | Low             |
| PF.M08.S1685                                             | 1418           | Loop 323 ESE       | Building        | c 1964      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1684                                             | 1424           | Loop 323 ESE       | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1686                                             | 1510           | Loop 323 ESE       | Building        | c 1958      | Commerce/Trade       | Colonial Revival  | 1.5            | Brick           | Low             |
| PF.M09.S1727                                             | 1812           | Loop 323 ESE       | Building        | c 1965      | Commerce/Trade       | No style          | 1.5            | Brick           | Low             |
| PF.M06.S0876                                             | 3301           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0877                                             | 3311           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0878                                             | 3319           | McMillan Dr        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0875                                             | 3320           | McMillan Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0879                                             | 3325           | McMillan Dr        | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0874                                             | 3326           | McMillan Dr        | Building        | c 1961      | Domestic-single      | Colonial Revival  | 1.5            | Brick           | Medium          |
| PF.M06.S0873                                             | 3330           | McMillan Dr        | Building        | c 1961      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0880                                             | 3331           | McMillan Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0881                                             | 3401           | McMillan Dr        | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0882                                             | 3409           | McMillan Dr        | Building        | c 1958      | Domestic-single      | Post-War Modern   | 1 to 2         | Brick           | Medium          |
| PF.M06.S0883                                             | 3417           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1 to 2         | Brick           | Low             |
| PF.M06.S0884                                             | 3501           | McMillan Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0885                                             | 3507           | McMillan Dr        | Building        | c 1960      | Domestic-single      | Ranch/SB          | 1              | Brick           | Medium          |
| PF.M06.S0872                                             | 3510           | McMillan Dr        | Building        | c 1955      | Vacant               | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0886                                             | 3515           | McMillan Dr        | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0871                                             | 3518           | McMillan Dr        | Building        | c 1962      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0887                                             | 3519           | McMillan Dr        | Building        | c 1956      | Domestic-single      | No style          | 1 to 2         | Brick           | Low             |
| PF.M06.S0870                                             | 3600           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0888                                             | 3601           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0869                                             | 3610           | McMillan Dr        | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0889                                             | 3611           | McMillan Dr        | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0868                                             | 3614           | McMillan Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0867                                             | 3700           | McMillan Dr        | Building        | c 1956      | Domestic-single      | PW Modern/Ranch   | 1 to 2         | Brick           | Medium          |
| PF.M06.S0891                                             | 3700 blk       | McMillan Dr        | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0890                                             | 3701           | McMillan Dr        | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0275                                             | 2205           | New Copeland Rd    | Building        | 1931        | Domestic-single      | Tudor Revival       | 1.5            | Brick           | High            |
| PF.M01.S0315                                             | 2214           | New Copeland Rd    | Building        | c 1938      | Domestic-single      | Tudor Revival       | 1              | Brick           | Medium          |
| PF.M01.S0276                                             | 2215           | New Copeland Rd    | Building        | c 1935      | Domestic-single      | Tudor Revival       | 1              | Brick           | High            |
| PF.M01.S0314                                             | 2220           | New Copeland Rd    | Building        | c 1936      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0313                                             | 2308           | New Copeland Rd    | Building        | c 1950      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M01.S0277                                             | 2311           | New Copeland Rd    | Building        | c 1930      | Domestic-single      | Tudor Revival       | 2.5            | Brick           | High            |
| PF.M01.S0312                                             | 2318           | New Copeland Rd    | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0311                                             | 2402           | New Copeland Rd    | Building        | c 1942      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M01.S0278                                             | 2403           | New Copeland Rd    | Building        | c 1950      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M01.S0310                                             | 2410           | New Copeland Rd    | Building        | c 1947      | Domestic-single      | Colonial Revival    | 1              | Stone           | Medium          |
| PF.M01.S0309                                             | 2418           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S0279                                             | 2421           | New Copeland Rd    | Building        | c 1940      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M01.S0281                                             | 2500 blk       | New Copeland Rd    | Building        | c 1938      | Domestic-single      | Ranch               | 1.5            | Brick           | Low             |
| PF.M01.S0308                                             | 2502           | New Copeland Rd    | Building        | c 1951      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0280                                             | 2503           | New Copeland Rd    | Building        | c 1941      | Domestic-single      | Colonial Revival    | 1 to 2         | Brick           | Low             |
| PF.M01.S0307                                             | 2510           | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Ranch               | 1              | Stucco          | Medium          |
| PF.M01.S0306                                             | 2520           | New Copeland Rd    | Building        | c 1961      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M01.S0285                                             | 2600 blk       | New Copeland Rd    | Structure       | c 1935      | Infrastructure       | No style            | None           | Stone           | Medium          |
| PF.M01.S0282                                             | 2605           | New Copeland Rd    | Building        | 1958        | Domestic-single      | Ranch               | 1              | Wood            | Medium          |
| PF.M01.S0305                                             | 2606           | New Copeland Rd    | Building        | c 1931      | Domestic-single      | Tudor Revival       | 2              | Brick           | Low             |
| PF.M01.S0304                                             | 2608           | New Copeland Rd    | Building        | c 1935      | Domestic-single      | Colonial Revival    | 2              | Stone           | Low             |
| PF.M01.S0283                                             | 2613           | New Copeland Rd    | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0284                                             | 2621           | New Copeland Rd    | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S0303                                             | 2624           | New Copeland Rd    | Building        | c 1935      | Domestic-single      | Colonial Revival    | 1.5            | Stone           | Low             |
| PF.M01.S0286                                             | 2631           | New Copeland Rd    | Building        | c 1924      | Domestic-single      | Tudor Revival       | 1.5            | Masonry         | Low             |
| PF.M01.S0302                                             | 2632           | New Copeland Rd    | Building        | c 1931      | Domestic-single      | Tudor Rev/Ranch     | 1              | Stucco          | Medium          |
| PF.M03.S0298                                             | 2700 blk       | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0301                                             | 2708           | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0300                                             | 2714           | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Col Rev/Tudor Rev | 1              | Brick           | Low             |
| PF.M03.S0287                                             | 2715           | New Copeland Rd    | Building        | c 1949      | Domestic-single      | No style          | 1              | Vinyl           | Low             |
| PF.M01.S0299                                             | 2718           | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0288                                             | 2723           | New Copeland Rd    | Building        | c 1949      | Domestic-single      | Colonial          | 1              | Brick           | Low             |
| PF.M03.S0289                                             | 2729           | New Copeland Rd    | Building        | c 1949      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0297                                             | 2732           | New Copeland Rd    | Building        | c 1946      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0290                                             | 2735           | New Copeland Rd    | Building        | c 1944      | Domestic-single      | Colonial Revival  | 1.5            | Wood            | Medium          |
| PF.M03.S0296                                             | 2738           | New Copeland Rd    | Building        | c 1945      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0295                                             | 2742           | New Copeland Rd    | Building        | c 1945      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0291                                             | 2743           | New Copeland Rd    | Building        | c 1944      | Domestic-single      | No style          | 1              | Not vis         | Low             |
| PF.M03.S0503                                             | 2800 blk       | New Copeland Rd    | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Wood            | Medium          |
| PF.M03.S0294                                             | 2802           | New Copeland Rd    | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0292                                             | 2805           | New Copeland Rd    | Building        | c 1951      | Domestic-single      | Colonial Revival  | 1.5            | Brick           | Medium          |
| PF.M03.S0293                                             | 2819           | New Copeland Rd    | Building        | c 1949      | Domestic-single      | No style          | 1              | Wood            | Low             |
| PF.M03.S0502                                             | 2822           | New Copeland Rd    | Building        | c 1951      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0501                                             | 2830           | New Copeland Rd    | Building        | c 1950      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0538                                             | 2903           | New Copeland Rd    | Building        | c 1920      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0500                                             | 2904           | New Copeland Rd    | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0539                                             | 2909           | New Copeland Rd    | Building        | c 1950      | Domestic-single      | No Style          | 1              | Vinyl           | Low             |
| PF.M03.S0499                                             | 2912           | New Copeland Rd    | Building        | c 1960      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M03.S0540                                             | 2915           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0541                                             | 2923           | New Copeland Rd    | Building        | c 1947      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M03.S0498                                             | 2924           | New Copeland Rd    | Building        | c 1945      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0542                                             | 2927           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M03.S0497                                             | 2930           | New Copeland Rd    | Building        | c 1940      | Domestic-single      | Colonial Revival  | 1              | Wood            | Low             |
| PF.M03.S0543                                             | 2931           | New Copeland Rd    | Building        | c 1949      | Domestic-single      | Colonial Revival  | 1              | Wood            | Medium          |
| PF.M03.S0544                                             | 2937           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Colonial Revival  | 1              | Vinyl           | Low             |
| PF.M05.S1253                                             | 3000 blk       | New Copeland Rd    | Building        | c 1940      | Domestic-single      | Tudor Revival     | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M03.S0545                                             | 3003           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |
| PF.M03.S0546                                             | 3009           | New Copeland Rd    | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |
| PF.M03.S0547                                             | 3013           | New Copeland Rd    | Building        | c 1952      | Domestic-single      | Ranch               | 1              | Asbes           | Low             |
| PF.M03.S0456                                             | 3030           | New Copeland Rd    | Building        | c 1955      | Religious-church     | No style            | 1 to 2         | Brick           | Low             |
| PF.M05.S1254                                             | 3031           | New Copeland Rd    | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1187                                             | 3100           | New Copeland Rd    | Building        | c 1930      | Vacant               | Tudor Revival       | 1              | Brick           | Low             |
| PF.M05.S1252                                             | 3101           | New Copeland Rd    | Building        | c 1966      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1251                                             | 3107           | New Copeland Rd    | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1234                                             | 3424           | New Copeland Rd    | Building        | c 1954      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1235                                             | 3432           | New Copeland Rd    | Building        | c 1957      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1236                                             | 3500           | New Copeland Rd    | Building        | c 1957      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1250                                             | 3511           | New Copeland Rd    | Building        | c 19 40     | Domestic-single      | No style            | 1              | Wood            | Low             |
| PF.M05.S1237                                             | 3512           | New Copeland Rd    | Building        | c 1958      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1249                                             | 3519           | New Copeland Rd    | Building        | c 1925      | Domestic-single      | No style            | 1              | Wood            | Low             |
| PF.M05.S1238                                             | 3520           | New Copeland Rd    | Building        | c 1960      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1248                                             | 3525           | New Copeland Rd    | Building        | c 1910      | Domestic-single      | Colonial Revival    | 1              | Wood            | Low             |
| PF.M05.S1239                                             | 3528           | New Copeland Rd    | Building        | c 1960      | Domestic-single      | Ranch/SB            | 1              | Brick           | Medium          |
| PF.M05.S1247                                             | 3529           | New Copeland Rd    | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Asbes           | Low             |
| PF.M05.S1240                                             | 3600           | New Copeland Rd    | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M05.S1245                                             | 3600 blk       | New Copeland Rd    | Building        | c 1955      | Domestic-single      | No style            | 1              | Wood            | Low             |
| PF.M05.S1246                                             | 3605           | New Copeland Rd    | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Syn             | Medium          |
| PF.M05.S1241                                             | 3610           | New Copeland Rd    | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1470                                             | 3618           | New Copeland Rd    | Building        | c 1966      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1244                                             | 3623           | New Copeland Rd    | Building        | c 1930      | Domestic-single      | No style            | 1              | Asbes           | Low             |
| PF.M05.S1243                                             | 3631           | New Copeland Rd    | Building        | c 1929      | Domestic-single      | Colonial Revival    | 1              | Wood            | Low             |
| PF.M05.S1242                                             | 3705           | New Copeland Rd    | Building        | c 1930      | Domestic-single      | Craftsman           | 1              | Wood            | Low             |
| PF.M07.S1471                                             | 3719           | New Copeland Rd    | Building        | c 1965      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M07.S1472                                             | 3723           | New Copeland Rd    | Building        | c 1945      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M07.S1473                                             | 3725           | New Copeland Rd    | Building        | c 1955      | Domestic-single      | No style            | 1              | Wood            | Low             |
| PF.M07.S1474                                             | 3731           | New Copeland Rd    | Building        | c 1934      | Domestic-single      | No style            | 1              | Vinyl           | Low             |
| PF.M08.S1534                                             | 4000 blk       | New Copeland Rd    | Building        | c 1963      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M08.S1533                                             | 4018           | New Copeland Rd    | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1535                                             | 4021           | New Copeland Rd    | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1532                                             | 4022           | New Copeland Rd    | Building        | 1966        | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | High            |
| PF.M08.S1536                                             | 4027           | New Copeland Rd    | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1531                                             | 4040           | New Copeland Rd    | Building        | c 1970      | Domestic-single      | Unknown             | 1              | Not vis         | Low             |
| PF.M08.S1530                                             | 4100           | New Copeland Rd    | Building        | c 1966      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1537                                             | 4101           | New Copeland Rd    | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1529                                             | 4106           | New Copeland Rd    | Building        | c 1970      | Domestic-single      | Post-war Modern     | 1              | Brick           | Low             |
| PF.M08.S1528                                             | 4116           | New Copeland Rd    | Building        | c 1969      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1527                                             | 4120           | New Copeland Rd    | Building        | c 1967      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M04.S0791                                             | 2811           | Oak Knob Dr        | Building        | c 1953      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0778                                             | 2814           | Oak Knob Dr        | Building        | c 1954      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M04.S0779                                             | 2820           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M04.S0780                                             | 2908           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0781                                             | 2910           | Oak Knob Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M04.S0782                                             | 2912           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M04.S0790                                             | 2917           | Oak Knob Dr        | Building        | 1954        | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | High            |
| PF.M04.S0783                                             | 2918           | Oak Knob Dr        | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M04.S0784                                             | 2924           | Oak Knob Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0789                                             | 2931           | Oak Knob Dr        | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0785                                             | 2932           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0786                                             | 3002           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0788                                             | 3007           | Oak Knob Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0787                                             | 3008           | Oak Knob Dr        | Building        | c 1958      | Domestic-single      | Ranch/CR/PW Mod     | 1              | Brick           | Low             |
| PF.M04.S0825                                             | 3101           | Paluxy Dr          | Building        | c 1957      | Religious-church     | Gothic Rev/Internat | 1 to 2         | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0857                                             | 3311           | Paluxy Dr          | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M06.S0658                                             | 3317           | Paluxy Dr          | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0859                                             | 3325           | Paluxy Dr          | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0860                                             | 3329           | Paluxy Dr          | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0861                                             | 3333           | Paluxy Dr          | Building        | c 1962      | Domestic-single      | Ranch/ER (Tahitian) | 1              | Brick           | Medium          |
| PF.M06.S0862                                             | 3337           | Paluxy Dr          | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S0864                                             | 3500 blk       | Paluxy Dr          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S0863                                             | 3509           | Paluxy Dr          | Building        | c 1963      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S0865                                             | 3601           | Paluxy Dr          | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M06.S0866                                             | 3700 blk       | Paluxy Dr          | Building        | c 1959      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M08.S1697                                             | 1400 blk       | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1716                                             | 1401           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1698                                             | 1408           | Pettit Dr          | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1715                                             | 1409           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1699                                             | 1414           | Pettit Dr          | Building        | c 1955      | Domestic-single      | French Col Revival  | 1              | Brick           | Medium          |
| PF.M08.S1714                                             | 1415           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1700                                             | 1420           | Pettit Dr          | Building        | c 1956      | Domestic-single      | French Col Revival  | 1              | Brick           | Medium          |
| PF.M06.S1713                                             | 1421           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M08.S1701                                             | 1426           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1711                                             | 1427           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M08.S1712                                             | 1429           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1702                                             | 1500           | Pettit Dr          | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1706                                             | 1500 blk       | Pettit Dr          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1703                                             | 1504           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1710                                             | 1505           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1709                                             | 1511           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1704                                             | 1512           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1705                                             | 1518           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M08.S1708                                             | 1519           | Pettit Dr          | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M08.S1569                                             | 801            | Pinedale Pl        | Building        | c 1969      | Domestic-single      | Georgian Revival    | 1              | Brick           | Low             |
| PF.M08.S1568                                             | 807            | Pinedale Pl        | Building        | c 1960      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | High            |
| PF.M08.S1561                                             | 808            | Pinedale Pl        | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1567                                             | 815            | Pinedale Pl        | Building        | c 1968      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1562                                             | 816            | Pinedale Pl        | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1566                                             | 823            | Pinedale Pl        | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1563                                             | 824            | Pinedale Pl        | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1564                                             | 902            | Pinedale Pl        | Building        | c 1963      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M08.S1565                                             | 903            | Pinedale Pl        | Building        | c 1964      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1573                                             | 1107           | Pinedale Pl        | Building        | c 1970      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M08.S1554                                             | 3900           | Pinedale Pl        | Building        | c 1959      | Domestic-single      | No style            | 1              | Brick           | Low             |
| PF.M08.S1553                                             | 3903           | Pinedale Pl        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M08.S1552                                             | 3907           | Pinedale Pl        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1555                                             | 3908           | Pinedale Pl        | Building        | c 1960      | Domestic-single      | FCR/Ranch           | 1              | Brick           | Medium          |
| PF.M08.S1551                                             | 3911           | Pinedale Pl        | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1556                                             | 3914           | Pinedale Pl        | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1550                                             | 3915           | Pinedale Pl        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1557                                             | 3918           | Pinedale Pl        | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M08.S1549                                             | 3919           | Pinedale Pl        | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1558                                             | 4010           | Pinedale Pl        | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1572                                             | 4011           | Pinedale Pl        | Building        | c 1964      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M08.S1571                                             | 4013           | Pinedale Pl        | Building        | c 1965      | Domestic-single      | Colonial /Ranch     | 1              | Brick           | Low             |
| PF.M08.S1559                                             | 4020           | Pinedale Pl        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M08.S1570                                             | 4029           | Pinedale Pl        | Building        | c 1965      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1560                                             | 4030           | Pinedale Pl        | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1118                                             | 1007           | Pollard Dr         | Building        | c 1962      | Domestic-single      | Storybook Ranch     | 1              | Brick           | Medium          |
| PF.M04.S0651                                             | 1008           | Pollard Dr         | Building        | c 1962      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S1117                                             | 1017           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M04.S0652                                             | 1018           | Pollard Dr         | Building        | c 1962      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M06.S1116                                             | 1025           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1.5            | Brick           | Medium          |
| PF.M04.S0653                                             | 1026           | Pollard Dr         | Building        | c 1962      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M06.S1115                                             | 1031           | Pollard Dr         | Building        | c 1965      | Domestic-single      | No style            | 2              | Brick           | Medium          |
| PF.M04.S0654                                             | 1104           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S1114                                             | 1105           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M04.S0655                                             | 1112           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M04.S0656                                             | 1120           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1113                                             | 1129           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M04.S0657                                             | 1132           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Colonial Revival    | 1.5            | Brick           | Medium          |
| PF.M02.S0338                                             | 2210           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0339                                             | 2220           | Pollard Dr         | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0337                                             | 2227           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M02.S0340                                             | 2300           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M02.S0341                                             | 2310           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0336                                             | 2315           | Pollard Dr         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M02.S0342                                             | 2318           | Pollard Dr         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0335                                             | 2319           | Pollard Dr         | Building        | c 1970      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0334                                             | 2401           | Pollard Dr         | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0343                                             | 2402           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0333                                             | 2411           | Pollard Dr         | Building        | c 1953      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M01.S0344                                             | 2412           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M01.S0332                                             | 2417           | Pollard Dr         | Building        | c 1960      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0345                                             | 2418           | Pollard Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0346                                             | 2504           | Pollard Dr         | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M01.S0331                                             | 2505           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M01.S0347                                             | 2510           | Pollard Dr         | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|----------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>         | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0330                                             | 2517           | Pollard Dr         | Building        | 1955        | Domestic-single      | PW Modern/Ranch      | 1              | Brick           | Medium          |
| PF.M01.S0329                                             | 2700 blk       | Pollard Dr         | Building        | c 1952      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0489                                             | 2802           | Pollard Dr         | Building        | c 1949      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0490                                             | 2803           | Pollard Dr         | Building        | c 1952      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M03.S0488                                             | 2808           | Pollard Dr         | Building        | c 1949      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0491                                             | 2815           | Pollard Dr         | Building        | c 1949      | Domestic-single      | Col Revival/Ranch    | 1              | Vinyl           | Medium          |
| PF.M03.S0487                                             | 2816           | Pollard Dr         | Building        | c 1947      | Domestic-single      | Col Revival/Ranch    | 1              | Asbes           | Low             |
| PF.M03.S0486                                             | 2900           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0492                                             | 2901           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0485                                             | 2914           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Ranch                | 1              | Brick           | Low             |
| PF.M03.S0493                                             | 2915           | Pollard Dr         | Building        | c 1960      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0494                                             | 2921           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M03.S0484                                             | 2922           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0495                                             | 2927           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Ranch/SB             | 1              | Brick           | Low             |
| PF.M03.S0483                                             | 2928           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0496                                             | 2931           | Pollard Dr         | Building        | c 1960      | Domestic-single      | Ranch                | 1              | Brick           | Low             |
| PF.M03.S0482                                             | 2934           | Pollard Dr         | Building        | c 1959      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0455                                             | 3000 blk       | Pollard Dr         | Object          | c 1954      | Infrastructure       | No style             | None           | Metal           | Medium          |
| PF.M06.S1054                                             | 3304           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Ranch/PW Modern      | 1 to 2         | Brick           | Medium          |
| PF.M06.S1055                                             | 3320           | Pollard Dr         | Building        | c 1966      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M06.S1067                                             | 3323           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Ranch                | 1 to 2         | Brick           | Medium          |
| PF.M06.S1056                                             | 3326           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival    | 1.5            | Brick           | Low             |
| PF.M06.S1066                                             | 3335           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Fr Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S1057                                             | 3336           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Ranch                | 1.5            | Brick           | Medium          |
| PF.M06.S1058                                             | 3400           | Pollard Dr         | Building        | c 1965      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Medium          |
| PF.M06.S1065                                             | 3401           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Medium          |
| PF.M06.S1059                                             | 3406           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Colonial Revival     | 1              | Brick           | Medium          |
| PF.M06.S1064                                             | 3407           | Pollard Dr         | Building        | c 1964      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|----------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>         | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S1063                                             | 3413           | Pollard Dr         | Building        | 1964        | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Medium          |
| PF.M06.S1060                                             | 3418           | Pollard Dr         | Building        | c 1970      | Domestic-single      | Fr Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S1061                                             | 3500 blk       | Pollard Dr         | Building        | c 1970      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Medium          |
| PF.M06.S1062                                             | 3526           | Pollard Dr         | Building        | 1970        | Domestic-single      | Post-war Modern      | 1              | Brick           | Low             |
| PF.M08.S1616                                             | 3600           | Pollard Dr         | Building        | c 1966      | Domestic-single      | Colonial Revival     | 1              | Brick           | Medium          |
| PF.M08.S1617                                             | 3608           | Pollard Dr         | Building        | c 1968      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Low             |
| PF.M08.S1618                                             | 3614           | Pollard Dr         | Building        | c 1966      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M08.S1619                                             | 3622           | Pollard Dr         | Building        | c 1966      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M08.S1620                                             | 3628           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Low             |
| PF.M08.S1621                                             | 3702           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Low             |
| PF.M08.S1622                                             | 3710           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M08.S1623                                             | 3718           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Fr Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M08.S1624                                             | 3724           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Fr Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M08.S1625                                             | 3800           | Pollard Dr         | Building        | c 1967      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Low             |
| PF.M08.S1626                                             | 3806           | Pollard Dr         | Building        | c 1969      | Domestic-single      | Fr Colonial Revival  | 1              | Brick           | Low             |
| PF.M08.S1627                                             | 4001           | Pollard Dr         | Building        | c 1969      | Domestic-single      | Ranch                | 1.5            | Brick           | Low             |
| PF.M02.S0348                                             | 2404           | Pounds Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M02.S0366                                             | 2411           | Pounds Av          | Building        | c 1955      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M02.S0349                                             | 2412           | Pounds Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M02.S0357                                             | 2419           | Pounds Av          | Building        | c 1954      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M02.S0350                                             | 2422           | Pounds Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M02.S0359                                             | 2500 blk       | Pounds Av          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M02.S0351                                             | 2504           | Pounds Av          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M02.S0352                                             | 2510           | Pounds Av          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M02.S0358                                             | 2515           | Pounds Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M02.S0353                                             | 2518           | Pounds Av          | Building        | c 1955      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M02.S0354                                             | 2526           | Pounds Av          | Building        | c 1964      | Domestic-single      | No style             | 1              | Brick           | Low             |
| PF.M02.S0360                                             | 2531           | Pounds Av          | Building        | c 1959      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M02.S0355                                             | 2616           | Pounds Av          | Building        | c 1957      | Domestic-vacant      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M04.S1733                                             | 2803           | Pounds Av          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M04.S0679                                             | 2818           | Pounds Av          | Building        | 1951        | Domestic-single      | PW Mod/ Internat'l | 1              | Brick           | High            |
| PF.M04.S0678                                             | 2819           | Pounds Av          | Building        | c 1950      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M04.S0680                                             | 2914           | Pounds Av          | Building        | 1956        | Domestic-single      | Post-war Modern    | 1              | Brick           | Medium          |
| PF.M04.S0682                                             | 3100           | Pounds Av          | Building        | c 1961      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M04.S0683                                             | 3101           | Pounds Av          | Building        | c 1960      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M04.S0685                                             | 3108           | Pounds Av          | Building        | c 1960      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M04.S0684                                             | 3109           | Pounds Av          | Building        | c 1961      | Domestic-single      | PW Modern/Ranch    | 1              | Brick           | Medium          |
| PF.M01.S0136                                             | 600 blk        | Rhodes Dr          | Structure       | Unknown     | Infrastructure       | No style           | None           | Conc            | Medium          |
| PF.M01.S0137                                             | 627            | Rhodes Dr          | Building        | c 1950      | Domestic-single      | No style           | 1              | Vinyl           | Low             |
| PF.M01.S0138                                             | 633            | Rhodes Dr          | Building        | c 1950      | Domestic-single      | Ranch              | 1              | Vinyl           | Low             |
| PF.M01.S0140                                             | 700 blk        | Rhodes Dr          | Building        | c 1950      | Domestic-single      | No style           | 1              | Wood            | Low             |
| PF.M01.S0139                                             | 701            | Rhodes Dr          | Building        | c 1950      | Domestic-single      | Col Revival/Ranch  | 1              | Vinyl           | Low             |
| PF.M01.S0159                                             | 800            | Rhodes Dr          | Building        | c 1970      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M01.S0141                                             | 801            | Rhodes Dr          | Building        | c 1970      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M01.S0158                                             | 806            | Rhodes Dr          | Building        | c 1970      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M01.S0142                                             | 807            | Rhodes Dr          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0157                                             | 814            | Rhodes Dr          | Building        | c 1970      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M01.S0143                                             | 815            | Rhodes Dr          | Building        | c 1963      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0156                                             | 900            | Rhodes Dr          | Building        | c 1963      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M01.S0144                                             | 901            | Rhodes Dr          | Building        | c 1962      | Domestic-single      | Ranch/SB           | 1              | Brick           | Medium          |
| PF.M01.S0155                                             | 904            | Rhodes Dr          | Building        | c 1962      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0145                                             | 909            | Rhodes Dr          | Building        | c 1964      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M01.S0154                                             | 910            | Rhodes Dr          | Building        | c 1964      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0146                                             | 917            | Rhodes Dr          | Building        | 1957        | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0153                                             | 920            | Rhodes Dr          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Low             |
| PF.M01.S0147                                             | 925            | Rhodes Dr          | Building        | c 1957      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0152                                             | 1000           | Rhodes Dr          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0148                                             | 1011           | Rhodes Dr          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0149                                             | 1015           | Rhodes Dr          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0151                                             | 1016           | Rhodes Dr          | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0150                                             | 1023           | Rhodes Dr          | Building        | c 1960      | Domestic-single      | Colonial Revival  | 1              | Brick           | Low             |
| PF.M03.S0588                                             | 100            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0589                                             | 101            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0587                                             | 110            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0590                                             | 111            | Ridgecrest Dr      | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0591                                             | 117            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0586                                             | 118            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0592                                             | 203            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0585                                             | 204            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0593                                             | 211            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0584                                             | 212            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0594                                             | 219            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0583                                             | 222            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0595                                             | 225            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0582                                             | 228            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0581                                             | 300            | Ridgecrest Dr      | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0596                                             | 301            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0580                                             | 306            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0597                                             | 307            | Ridgecrest Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0598                                             | 311            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0579                                             | 312            | Ridgecrest Dr      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0599                                             | 315            | Ridgecrest Dr      | Building        | c 1961      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0578                                             | 316            | Ridgecrest Dr      | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0998                                             | 1400           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0999                                             | 1408           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | No style          | 1              | Brick           | Low             |
| PF.M08.S1725                                             | 1409           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1000                                             | 1414           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M08.S1724                                             | 1415           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S1001                                             | 1420           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1723                                             | 1421           | Rodessa Dr         | Building        | c 1958      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Medium          |
| PF.M06.S1002                                             | 1426           | Rodessa Dr         | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1722                                             | 1429           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Medium          |
| PF.M06.S1003                                             | 1430           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M08.S1721                                             | 1501           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch/FCR         | 1              | Brick           | Low             |
| PF.M06.S1004                                             | 1504           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Post-war Modern   | 1              | Brick           | Low             |
| PF.M08.S1720                                             | 1505           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S1005                                             | 1510           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1719                                             | 1511           | Rodessa Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M08.S1726                                             | 1619           | Rodessa Dr         | Building        | c 1959      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1323                                             | 100            | Samuel St          | Building        | c 1964      | Domestic-single      | Col Rev/Tudor Rev | 1              | Brick           | Medium          |
| PF.M05.S1322                                             | 101            | Samuel St          | Building        | c 1965      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1324                                             | 110            | Samuel St          | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1321                                             | 111            | Samuel St          | Building        | c 1962      | Domestic-single      | Ranch/SB          | 1              | Brick           | Medium          |
| PF.M05.S1325                                             | 118            | Samuel St          | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1320                                             | 119            | Samuel St          | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1326                                             | 206            | Samuel St          | Building        | c 1962      | Domestic-single      | Storybook Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1319                                             | 207            | Samuel St          | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1327                                             | 212            | Samuel St          | Building        | c 1962      | Domestic-single      | Col Rev/Tudor Rev | 1              | Brick           | Medium          |
| PF.M05.S1318                                             | 213            | Samuel St          | Building        | c 1961      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1328                                             | 218            | Samuel St          | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1317                                             | 219            | Samuel St          | Building        | c 1961      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1329                                             | 224            | Samuel St          | Building        | c 1963      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1316                                             | 225            | Samuel St          | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S1087                                             | 1009           | Santa Rosa Dr      | Building        | c 1965      | Domestic-single      | Post-war Modern   | 1              | Brick           | Low             |
| PF.M06.S1086                                             | 1019           | Santa Rosa Dr      | Building        | 1965        | Domestic-single      | Neo-Classical     | 1              | Brick           | High            |
| PF.M06.S1085                                             | 1111           | Santa Rosa Dr      | Building        | c 1970      | Domestic-single      | FCR/Ranch         | 1              | Brick           | Low             |
| PF.M06.S1084                                             | 1119           | Santa Rosa Dr      | Building        | c 1965      | Domestic-single      | Col Revival/Ranch | 1.5            | Brick           | Medium          |
| PF.M06.S0970                                             | 1400           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0981                                             | 1401           | Santa Rosa Dr      | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S0971                                             | 1408           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0980                                             | 1411           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S0972                                             | 1414           | Santa Rosa Dr      | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0979                                             | 1415           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0978                                             | 1417           | Santa Rosa Dr      | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0973                                             | 1420           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0974                                             | 1426           | Santa Rosa Dr      | Building        | c 1957      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M06.S0977                                             | 1431           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Vinyl           | Low             |
| PF.M06.S0975                                             | 1436           | Santa Rosa Dr      | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0976                                             | 1437           | Santa Rosa Dr      | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M01.S0038                                             | 403            | Seagle St          | Building        | c 1952      | Domestic-single      | Ranch             | 1              | Vinyl           | Low             |
| PF.M01.S0039                                             | 407            | Seagle St          | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1.5            | Brick           | Low             |
| PF.M01.S0037                                             | 410            | Seagle St          | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0040                                             | 415            | Seagle St          | Building        | c 1970      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0041                                             | 427            | Seagle St          | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1188                                             | 607            | Shannon Dr         | Building        | c 1954      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1189                                             | 620            | Shannon Dr         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M05.S1190                                             | 700            | Shannon Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M05.S1191                                             | 704            | Shannon Dr         | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1192                                             | 714            | Shannon Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M05.S1193                                             | 722            | Shannon Dr         | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1194                                             | 730            | Shannon Dr         | Building        | c 1955      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Low             |
| PF.M05.S1195                                             | 804            | Shannon Dr         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1196                                             | 810            | Shannon Dr         | Building        | c 1954      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M05.S1197                                             | 816            | Shannon Dr         | Building        | c 1955      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1737                                             | 500 blk        | Shepherd Ln        | Structure       | c 1957      | Infrastructure       | No style            | None           | Stone           | Low             |
| PF.M07.S1489                                             | 800 blk        | Shepherd Ln        | Structure       | c 1953      | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M07.S1488                                             | 800 blk        | Shepherd Ln        | Structure       | c 1953      | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M07.S1490                                             | 815            | Shepherd Ln        | Building        | c 1962      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1615                                             | 925            | Shepherd Ln        | Building        | c 1959      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M06.S1100                                             | 928            | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M08.S1614                                             | 1001           | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M06.S1101                                             | 1002           | Shepherd Ln        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1103                                             | 1010           | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1613                                             | 1017           | Shepherd Ln        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1103                                             | 1018           | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1612                                             | 1023           | Shepherd Ln        | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1104                                             | 1028           | Shepherd Ln        | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S1105                                             | 1102           | Shepherd Ln        | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M08.S1611                                             | 1107           | Shepherd Ln        | Building        | c 1956      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1610                                             | 1109           | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1609                                             | 1111           | Shepherd Ln        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S1106                                             | 1112           | Shepherd Ln        | Building        | c 1957      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M06.S1107                                             | 1120           | Shepherd Ln        | Building        | c 1957      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1608                                             | 1121           | Shepherd Ln        | Building        | c 1958      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1309                                             | 101            | Sheridan St        | Building        | c 1965      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M05.S1310                                             | 110            | Sheridan St        | Building        | c 1960      | Domestic-single      | Storybook Ranch     | 1              | Brick           | High            |
| PF.M05.S1308                                             | 111            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1311                                             | 118            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1307                                             | 119            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1312                                             | 206            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1306                                             | 207            | Sheridan St        | Building        | c 1963      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1313                                             | 212            | Sheridan St        | Building        | c 1963      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1305                                             | 213            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1314                                             | 218            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1304                                             | 219            | Sheridan St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1315                                             | 224            | Sheridan St        | Building        | c 1962      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1303                                             | 225            | Sheridan St        | Building        | c 1963      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0610                                             | 100            | Stanford St        | Building        | c 1961      | Domestic-single      | Colonial Revival  | 1.5            | Brick           | Medium          |
| PF.M03.S0609                                             | 110            | Stanford St        | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1302                                             | 111            | Stanford St        | Building        | c 1961      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0608                                             | 118            | Stanford St        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1301                                             | 119            | Stanford St        | Building        | c 1960      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M03.S0607                                             | 206            | Stanford St        | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Wood            | Medium          |
| PF.M05.S1300                                             | 207            | Stanford St        | Building        | c 1961      | Domestic-single      | Ranch/Col Revival | 1              | Brick           | Medium          |
| PF.M03.S0606                                             | 212            | Stanford St        | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1299                                             | 213            | Stanford St        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0605                                             | 218            | Stanford St        | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1298                                             | 219            | Stanford St        | Building        | c 1960      | Domestic-single      | Ranch             | 1              | Wood            | Medium          |
| PF.M03.S0604                                             | 224            | Stanford St        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M05.S1297                                             | 225            | Stanford St        | Building        | c 1962      | Domestic-single      | Ranch/Col Revival | 1              | Wood            | Medium          |
| PF.M03.S0603                                             | 300            | Stanford St        | Building        | c 1960      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0602                                             | 306            | Stanford St        | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M03.S0601                                             | 312            | Stanford St        | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M03.S0600                                             | 316            | Stanford St        | Building        | c 1959      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M03.S0614                                             | 404            | Stanford St        | Building        | c 1950      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M03.S0613                                             | 410            | Stanford St        | Building        | c 1945      | Domestic-single      | No style          | 1              | Wood            | Low             |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M05.S1296                                             | 419            | Stanford St        | Building        | c 1950      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1295                                             | 427            | Stanford St        | Building        | c 1915      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M03.S0612                                             | 512            | Stanford St        | Building        | c 1949      | Domestic-single      | Minimal Traditional | 1              | Vinyl           | Low             |
| PF.M03.S0611                                             | 522            | Stanford St        | Building        | c 1936      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |
| PF.M05.S1401                                             | 400 blk        | Tech Pl            | Structure       | c 1958      | Infrastructure       | No Style            | None           | Conc            | Medium          |
| PF.M05.S1397                                             | 400 blk        | Tech Pl            | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1394                                             | 400 blk        | Tech Pl            | Structure       | Unknown     | Infrastructure       | No style            | None           | Conc            | Medium          |
| PF.M05.S1398                                             | 420            | Tech Pl            | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1396                                             | 425            | Tech Pl            | Building        | c 1960      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1399                                             | 426            | Tech Pl            | Building        | c 1960      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1395                                             | 427            | Tech Pl            | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M05.S1400                                             | 434            | Tech Pl            | Building        | c 1959      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1393                                             | 435            | Tech Pl            | Building        | c 1961      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M1A.S0002                                             | 400            | Troup Hwy          | Building        | c 1970      | Commerce/Trade       | International       | 1              | Brick           | Low             |
| PF.M01.S0006                                             | 401            | Troup Hwy          | Building        | c 1965      | Commerce/Trade       | No style            | 1              | Conc blk        | Low             |
| PF.M1A.S0003                                             | 410-412        | Troup Hwy          | Building        | c 1954      | Domestic-duplex      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0007                                             | 417            | Troup Hwy          | Building        | c 1965      | Vacant               | No style            | 1              | Stucco          | Low             |
| PF.M1A.S0004                                             | 418-420        | Troup Hwy          | Building        | c 1954      | Domestic-duplex      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0008                                             | 419-427        | Troup Hwy          | Building        | c 1953      | Commerce/Trade       | International       | 1              | Brick           | Low             |
| PF.M1A.S0005                                             | 426            | Troup Hwy          | Building        | c 1954      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M1A.S0035                                             | 502            | Troup Hwy          | Building        | c 1952      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M1A.S0034                                             | 508            | Troup Hwy          | Building        | c 1952      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M1A.S0033                                             | 528            | Troup Hwy          | Building        | c 1920      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M01.S0009                                             | 601            | Troup Hwy          | Building        | c 1938      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M1A.S0032                                             | 612            | Troup Hwy          | Building        | c 1936      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0010                                             | 613            | Troup Hwy          | Building        | c 1929      | Domestic-single      | Tudor Revival       | 1              | Brick           | Medium          |
| PF.M01.S0078                                             | 617            | Troup Hwy          | Building        | c 1938      | Domestic-single      | Tudor Revival       | 1              | Brick           | Medium          |
| PF.M1A.S0031                                             | 622-624        | Troup Hwy          | Building        | c 1936      | Domestic-duplex      | Colonial Revival    | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M1A.S0030                                             | 628            | Troup Hwy          | Building        | c 1933      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M1A.S0029                                             | 700 blk        | Troup Hwy          | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M1A.S0028                                             | 716            | Troup Hwy          | Building        | c 1949      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M01.S0011                                             | 801            | Troup Hwy          | Building        | 1935        | Domestic-single      | Georgian Revival   | 2.5            | Brick           | Medium          |
| PF.M1A.S0027                                             | 806            | Troup Hwy          | Building        | c 1935      | Domestic-single      | Colonial Revival   | 2              | Brick           | Medium          |
| PF.M01.S0012                                             | 815            | Troup Hwy          | Building        | c 1958      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M02.S0016                                             | 900 blk        | Troup Hwy          | Building        | c 1952      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M02.S0013                                             | 905            | Troup Hwy          | Building        | c 1925      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M02.S0014                                             | 909            | Troup Hwy          | Building        | c 1925      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M1A.S0026                                             | 910            | Troup Hwy          | Building        | c 1934      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M02.S0015                                             | 915            | Troup Hwy          | Building        | c 1925      | Domestic-single      | Tudor Revival      | 1              | Brick           | Low             |
| PF.M02.S0017                                             | 925            | Troup Hwy          | Building        | c 1925      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M1A.S0024                                             | 1000           | Troup Hwy          | Building        | c 1951      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M02.S0019                                             | 1000 blk       | Troup Hwy          | Building        | c 1927      | Domestic-single      | Col Revival/Crafts | 1              | Brick           | Low             |
| PF.M02.S0018                                             | 1001           | Troup Hwy          | Building        | c 1927      | Domestic-single      | Tudor Rev/Col Rev  | 1              | Brick           | Low             |
| PF.M02.S0020                                             | 1031           | Troup Hwy          | Building        | c 1930      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M1A.S0023                                             | 1100           | Troup Hwy          | Building        | c 1933      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M1A.S0022                                             | 1104           | Troup Hwy          | Building        | c 1938      | Domestic-single      | Tudor Revival      | 1              | Brick           | Medium          |
| PF.M02.S0021                                             | 1109           | Troup Hwy          | Building        | c 1930      | Domestic-single      | Tudor Revival      | 1.5            | Brick           | Medium          |
| PF.M02.S0366                                             | 1405           | Troup Hwy          | Building        | c 1955      | Commerce/Trade       | No style           | 1              | Stucco          | Low             |
| PF.M02.S0367                                             | 1415           | Troup Hwy          | Building        | 1961        | Commerce/Trade       | Post-war Modern    | 2              | Metal           | Medium          |
| PF.M02.S0368                                             | 1423           | Troup Hwy          | Building        | c 1960      | Commerce/Trade       | No Style           | 1              | Brick           | Low             |
| PF.M02.S0365                                             | 1607           | Troup Hwy          | Building        | 1962        | Religious-church     | Neo-Classical      | 3              | Brick           | Low             |
| PF.M04.S0617                                             | 1700-1800 blks | Troup Hwy          | Site            | c 1958      | Commerce/Trade       | No Style           | 1              | Stucco          | Low             |
| PF.M03.S0439                                             | 611            | Watkins St         | Building        | c 1957      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M03.S0440                                             | 619            | Watkins St         | Building        | c 1957      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M03.S0441                                             | 625            | Watkins St         | Building        | c 1957      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M03.S0438                                             | 700            | Watkins St         | Building        | c 1965      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|----------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                      |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>         | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M03.S0442                                             | 703            | Watkins St         | Building        | c 1961      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Low             |
| PF.M03.S0437                                             | 704            | Watkins St         | Building        | c 1954      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Low             |
| PF.M03.S0436                                             | 708            | Watkins St         | Building        | c 1949      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0435                                             | 722            | Watkins St         | Building        | c 1950      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M03.S0443                                             | 803            | Watkins St         | Building        | c 1962      | Domestic-single      | Colonial Revival     | 1.5            | Brick           | Medium          |
| PF.M03.S0434                                             | 804            | Watkins St         | Building        | c 1950      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0433                                             | 818            | Watkins St         | Building        | c 1950      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M03.S0432                                             | 822            | Watkins St         | Building        | c 1954      | Domestic-single      | Ranch                | 1              | Wood            | Medium          |
| PF.M03.S0444                                             | 823            | Watkins St         | Building        | c 1957      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0431                                             | 904            | Watkins St         | Building        | c 1953      | Domestic-single      | Ranch                | 1              | Brick           | Low             |
| PF.M03.S0445                                             | 905            | Watkins St         | Building        | c 1958      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M03.S0430                                             | 918            | Watkins St         | Building        | c 1947      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M04.S0624                                             | 1015           | Watkins St         | Building        | c 1958      | Domestic-single      | Ranch                | 1 to 2         | Brick           | Medium          |
| PF.M04.S0633                                             | 1018           | Watkins St         | Building        | 1952        | Domestic-single      | Internat'l/Wrightian | 1              | Brick           | Medium          |
| PF.M04.S0625                                             | 1021           | Watkins St         | Building        | 1962        | Domestic-single      | PW-Mod/ Internat'l   | 1 to 2         | Wood            | Medium          |
| PF.M04.S0632                                             | 1126           | Watkins St         | Building        | c 1952      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M04.S0626                                             | 1127           | Watkins St         | Building        | c 1951      | Domestic-single      | Col Rev/PW Modern    | 1              | Brick           | Medium          |
| PF.M04.S0627                                             | 1207           | Watkins St         | Building        | c 1954      | Domestic-single      | Colonial Revival     | 1              | Brick           | Low             |
| PF.M04.S0631                                             | 1210           | Watkins St         | Building        | c 1953      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M04.S0628                                             | 1211           | Watkins St         | Building        | c 1954      | Domestic-single      | Colonial Revival     | 1              | Brick           | Medium          |
| PF.M04.S0629                                             | 1217           | Watkins St         | Building        | c 1952      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M04.S0630                                             | 1220           | Watkins St         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |
| PF.M06.S0954                                             | 1403           | Waverly St         | Building        | c 1955      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M06.S0953                                             | 1409           | Waverly St         | Building        | c 1958      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Medium          |
| PF.M06.S0952                                             | 1415           | Waverly St         | Building        | c 1954      | Domestic-single      | Ranch                | 1              | Brick           | Medium          |
| PF.M06.S0951                                             | 1421           | Waverly St         | Building        | c 1954      | Domestic-single      | Ranch/Col Revival    | 1              | Brick           | Low             |
| PF.M06.S0950                                             | 1427           | Waverly St         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Low             |
| PF.M06.S0949                                             | 1433           | Waverly St         | Building        | c 1958      | Domestic-single      | Col Revival/Ranch    | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0948                                             | 1503           | Waverly St         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0946                                             | 1504           | Waverly St         | Building        | c 1954      | Domestic-single      | PW Modern/Ranch   | 1              | Brick           | Low             |
| PF.M06.S0945                                             | 1512           | Waverly St         | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S0947                                             | 1515           | Waverly St         | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M02.S0167                                             | 2300 blk       | Waydak Cir         | Structure       | c 1954      | Infrastructure       | No style          | None           | Conc            | Medium          |
| PF.M02.S0163                                             | 2302           | Waydak Cir         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0164                                             | 2303           | Waydak Cir         | Building        | c 1956      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M02.S0162                                             | 2308           | Waydak Cir         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0165                                             | 2309           | Waydak Cir         | Building        | c 1965      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0166                                             | 2315           | Waydak Cir         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0161                                             | 2316           | Waydak Cir         | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0160                                             | 2322           | Waydak Cir         | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0955                                             | 1400           | Westfield St       | Building        | c 1958      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M06.S0957                                             | 1400 blk       | Westfield St       | Building        | c 1957      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0969                                             | 1401           | Westfield St       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0956                                             | 1408           | Westfield St       | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0968                                             | 1409           | Westfield St       | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0967                                             | 1415           | Westfield St       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0958                                             | 1420           | Westfield St       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S0966                                             | 1421           | Westfield St       | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0959                                             | 1426           | Westfield St       | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M06.S0965                                             | 1427           | Westfield St       | Building        | c 1957      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0960                                             | 1432           | Westfield St       | Building        | c 1956      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M06.S0964                                             | 1433           | Westfield St       | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0961                                             | 1500           | Westfield St       | Building        | 1957        | Domestic-single      | Ranch Style       | 1              | Brick           | High            |
| PF.M06.S0963                                             | 1507           | Westfield St       | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M06.S0962                                             | 1508           | Westfield St       | Building        | c 1955      | Domestic-single      | Ranch             | 1              | Vinyl           | Medium          |
| PF.M01.S0177                                             | 400 blk        | Wilma St           | Building        | c 1945      | Domestic-single      | No style          | 1              | Stone           | Low             |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S0176                                             | 402            | Wilma St           | Building        | c 1945      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0178                                             | 414            | Wilma St           | Building        | c 1952      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M03.S0171                                             | 417            | Wilma St           | Building        | c 1950      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0179                                             | 420            | Wilma St           | Building        | c 1952      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M03.S0172                                             | 421            | Wilma St           | Building        | c 1951      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M01.S0180                                             | 430            | Wilma St           | Building        | c 1937      | Domestic-single      | Colonial Revival    | 2              | Wood            | Medium          |
| PF.M03.S0173                                             | 505            | Wilma St           | Building        | c 1946      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M03.S0174                                             | 511            | Wilma St           | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |
| PF.M03.S0175                                             | 519            | Wilma St           | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Low             |
| PF.M01.S0181                                             | 603            | Wilma St           | Building        | c 1946      | Domestic-single      | No style            | 1.5            | Brick           | Low             |
| PF.M01.S0189                                             | 614            | Wilma St           | Building        | c 1947      | Domestic-single      | Col Revival/Ranch   | 1              | Wood            | Medium          |
| PF.M01.S0182                                             | 615            | Wilma St           | Building        | c 1947      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M01.S0183                                             | 617            | Wilma St           | Building        | c 1947      | Domestic-single      | Greek Revival       | 1              | Brick           | Low             |
| PF.M01.S0184                                             | 623            | Wilma St           | Building        | c 1948      | Domestic-single      | Greek Revival       | 1              | Asbes           | Medium          |
| PF.M01.S0190                                             | 624            | Wilma St           | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Wood            | Medium          |
| PF.M01.S0185                                             | 625            | Wilma St           | Building        | c 1948      | Domestic-single      | Minimal Traditional | 1              | Wood            | Low             |
| PF.M01.S0191                                             | 630            | Wilma St           | Building        | c 1948      | Domestic-single      | Ranch               | 1              | Wood            | Medium          |
| PF.M01.S0186                                             | 631            | Wilma St           | Building        | c 1948      | Domestic-single      | Minimal Traditional | 1              | Wood            | Low             |
| PF.M01.S0187                                             | 633            | Wilma St           | Building        | c 1948      | Domestic-single      | Ranch               | 1              | Vinyl           | Low             |
| PF.M01.S0192                                             | 634            | Wilma St           | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Asbes           | Medium          |
| PF.M01.S0188                                             | 641            | Wilma St           | Building        | c 1947      | Domestic-single      | Ranch               | 1              | Vinyl           | Low             |
| PF.M01.S0193                                             | 642            | Wilma St           | Building        | c 1948      | Domestic-single      | Colonial Revival    | 1              | Vinyl           | Low             |
| PF.M01.S0194                                             | 648            | Wilma St           | Building        | c 1948      | Domestic-single      | Minimal Traditional | 1              | Vinyl           | Medium          |
| PF.M01.S0195                                             | 719            | Wilma St           | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S1732                                             | 720            | Wilma St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M01.S0196                                             | 723            | Wilma St           | Building        | c 1953      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S1731                                             | 726            | Wilma St           | Building        | c 1956      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M01.S0197                                             | 729            | Wilma St           | Building        | c 1952      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |

| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                   |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|-------------------|----------------|-----------------|-----------------|
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                   |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>      | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M01.S1730                                             | 800            | Wilma St           | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Low             |
| PF.M01.S0198                                             | 801            | Wilma St           | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0199                                             | 805            | Wilma St           | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0200                                             | 811            | Wilma St           | Building        | c 1951      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S1729                                             | 814            | Wilma St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0211                                             | 904            | Wilma St           | Building        | c 1954      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0210                                             | 912            | Wilma St           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0209                                             | 918            | Wilma St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0201                                             | 919            | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M01.S0208                                             | 1000           | Wilma St           | Building        | c 1958      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0202                                             | 1001           | Wilma St           | Building        | c 1955      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0207                                             | 1006           | Wilma St           | Building        | c 1954      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0203                                             | 1013           | Wilma St           | Building        | c 1955      | Domestic-single      | Colonial Revival  | 1              | Brick           | Medium          |
| PF.M01.S0206                                             | 1014           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M01.S0205                                             | 1020           | Wilma St           | Building        | c 1956      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0204                                             | 1023           | Wilma St           | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0388                                             | 1104           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0389                                             | 1105           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0387                                             | 1112           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0390                                             | 1115           | Wilma St           | Building        | c 1952      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0386                                             | 1120           | Wilma St           | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0391                                             | 1125           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0385                                             | 1204           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Low             |
| PF.M02.S0392                                             | 1207           | Wilma St           | Building        | c 1953      | Domestic-single      | Ranch             | 1              | Brick           | Medium          |
| PF.M02.S0384                                             | 1212           | Wilma St           | Building        | c 1959      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0393                                             | 1217           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0394                                             | 1227           | Wilma St           | Building        | c 1953      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |
| PF.M02.S0364                                             | 1228           | Wilma St           | Building        | c 1954      | Domestic-single      | Col Revival/Ranch | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M02.S0395                                             | 1305           | Wilma St           | Building        | c 1956      | Domestic-single      | Ranch/PW Modern     | 1              | Brick           | Medium          |
| PF.M02.S0363                                             | 1306           | Wilma St           | Building        | 1954        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M08.S1596                                             | 928            | Wilmington Pl      | Building        | c 1962      | Domestic-single      | Post-war Modern     | 1              | Brick           | Low             |
| PF.M08.S1597                                             | 1002           | Wilmington Pl      | Building        | c 1962      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1598                                             | 1018           | Wilmington Pl      | Building        | c 1961      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Medium          |
| PF.M08.S1595                                             | 1023           | Wilmington Pl      | Building        | c 1961      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M08.S1594                                             | 1107           | Wilmington Pl      | Building        | c 1964      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M08.S1593                                             | 1117           | Wilmington Pl      | Building        | c 1968      | Domestic-single      | ER (Chinoiserie)    | 1              | Brick           | Low             |
| PF.M07.S1431                                             | 315            | Winchester Dr      | Building        | c 1969      | Domestic-single      | FCR/Neo-Med         | 1              | Brick           | Low             |
| PF.M05.S1255                                             | 316            | Winchester Dr      | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1432                                             | 321            | Winchester Dr      | Building        | c 1970      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1256                                             | 322            | Winchester Dr      | Building        | c 1967      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M07.S1433                                             | 327            | Winchester Dr      | Building        | c 1966      | Domestic-single      | Ranch/Neo-Med       | 1              | Brick           | Medium          |
| PF.M05.S1257                                             | 328            | Winchester Dr      | Building        | c 1966      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M05.S1258                                             | 400            | Winchester Dr      | Building        | c 1968      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1259                                             | 406            | Winchester Dr      | Building        | c 1969      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1260                                             | 412            | Winchester Dr      | Building        | c 1968      | Domestic-single      | Colonial Revival    | 1              | Brick           | Low             |
| PF.M05.S1261                                             | 418            | Winchester Dr      | Building        | c 1969      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |
| PF.M05.S1262                                             | 424            | Winchester Dr      | Building        | c 1967      | Domestic-single      | No style            | 1.5            | Brick           | Low             |
| PF.M07.S1434                                             | 501            | Winchester Dr      | Building        | c 1968      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M05.S1263                                             | 504            | Winchester Dr      | Building        | c 1966      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M07.S1435                                             | 509            | Winchester Dr      | Building        | c 1965      | Domestic-single      | Neo-Mediterranean   | 1              | Brick           | Medium          |
| PF.M05.S1264                                             | 510            | Winchester Dr      | Building        | c 1965      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M06.S0909                                             | 3316           | Woodbine Blvd      | Building        | 1958        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |
| PF.M06.S0910                                             | 3319           | Woodbine Blvd      | Building        | c 1955      | Domestic-single      | Colonial Revival    | 1              | Brick           | Medium          |
| PF.M06.S0908                                             | 3322           | Woodbine Blvd      | Building        | 1955        | Domestic-single      | Post-war Modern     | 1-1.5          | Brick           | High            |
| PF.M06.S0922                                             | 3400           | Woodbine Blvd      | Building        | c 1955      | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | Low             |
| PF.M06.S0911                                             | 3401           | Woodbine Blvd      | Building        | 1955        | Domestic-single      | Col Revival/Ranch   | 1              | Brick           | High            |

|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|--------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                    |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>       | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M06.S0912                                             | 3411           | Woodbine Blvd      | Building        | 1960        | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | High            |
| PF.M06.S0921                                             | 3416           | Woodbine Blvd      | Building        | 1958        | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | High            |
| PF.M06.S0913                                             | 3501           | Woodbine Blvd      | Building        | c 1955      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M06.S0920                                             | 3504           | Woodbine Blvd      | Building        | 1958        | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | High            |
| PF.M06.S0914                                             | 3511           | Woodbine Blvd      | Building        | c 1956      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Low             |
| PF.M06.S0919                                             | 3514           | Woodbine Blvd      | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M06.S0917                                             | 3600 blk       | Woodbine Blvd      | Building        | c 1959      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M06.S0918                                             | 3604           | Woodbine Blvd      | Building        | c 1955      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M06.S0915                                             | 3615           | Woodbine Blvd      | Building        | c 1958      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M06.S0916                                             | 3700           | Woodbine Blvd      | Building        | c 1958      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M05.S1216                                             | 3416           | Wynnwood Dr        | Building        | c 1957      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M05.S1233                                             | 3417           | Wynnwood Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M05.S1232                                             | 3423           | Wynnwood Dr        | Building        | c 1960      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1217                                             | 3424           | Wynnwood Dr        | Building        | c 1957      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M05.S1231                                             | 3431           | Wynnwood Dr        | Building        | c 1954      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1218                                             | 3432           | Wynnwood Dr        | Building        | c 1954      | Domestic-single      | Ranch /Col Revival | 1              | Brick           | Low             |
| PF.M05.S1230                                             | 3501           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M05.S1219                                             | 3502           | Wynnwood Dr        | Building        | c 1954      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1220                                             | 3512           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |
| PF.M05.S1229                                             | 3515           | Wynnwood Dr        | Building        | c 1956      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Medium          |
| PF.M05.S1221                                             | 3520           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Col Revival/Ranch  | 1              | Brick           | Medium          |
| PF.M05.S1228                                             | 3521           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Medium          |
| PF.M05.S1222                                             | 3524           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M05.S1227                                             | 3529           | Wynnwood Dr        | Building        | c 1954      | Domestic-single      | Ranch/Col Revival  | 1              | Brick           | Low             |
| PF.M05.S1226                                             | 3533           | Wynnwood Dr        | Building        | c 1957      | Domestic-single      | French Col Revival | 1              | Brick           | Medium          |
| PF.M05.S1225                                             | 3537           | Wynnwood Dr        | Building        | c 1959      | Domestic-single      | Ranch              | 1              | Brick           | Low             |
| PF.M05.S1223                                             | 3600           | Wynnwood Dr        | Building        | c 1957      | Domestic-single      | Colonial Revival   | 1.5            | Brick           | Medium          |
| PF.M05.S1224                                             | 3610           | Wynnwood Dr        | Building        | c 1955      | Domestic-single      | Colonial Revival   | 1              | Brick           | Medium          |

|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|----------------------------------------------------------|----------------|--------------------|-----------------|-------------|----------------------|---------------------|----------------|-----------------|-----------------|
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Historic Resources Survey Summary</b>                 |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Tyler, Texas: Pollard Farm Survey Area, 2015-2016</b> |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
|                                                          |                |                    |                 |             |                      |                     |                |                 |                 |
| <b>Local ID</b>                                          | <b>Address</b> | <b>Street Name</b> | <b>Resource</b> | <b>Date</b> | <b>Property Type</b> | <b>Style</b>        | <b>Stories</b> | <b>Material</b> | <b>Priority</b> |
| PF.M07.S1505                                             | 3615           | Wynnwood Dr        | Building        | c 1962      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1497                                             | 3618           | Wynnwood Dr        | Building        | c 1958      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | High            |
| PF.M07.S1504                                             | 3623           | Wynnwood Dr        | Building        | c 1959      | Domestic-single      | Ranch               | 1              | Brick           | Medium          |
| PF.M07.S1498                                             | 3704           | Wynnwood Dr        | Building        | c 1969      | Domestic-single      | Ranch               | 1              | Brick           | Low             |
| PF.M07.S1503                                             | 3707           | Wynnwood Dr        | Building        | c 1963      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Low             |
| PF.M07.S1499                                             | 3710           | Wynnwood Dr        | Building        | c 1968      | Domestic-single      | Ranch/CR/Crafts     | 1 to 2         | Brick           | Low             |
| PF.M07.S1502                                             | 3715           | Wynnwood Dr        | Building        | c 1961      | Domestic-single      | Ranch/Col Revival   | 1              | Brick           | Medium          |
| PF.M07.S1500                                             | 3802           | Wynnwood Dr        | Building        | c 1963      | Domestic-single      | Col Revival/Ranch   | 1 to 2         | Brick           | Medium          |
| PF.M07.S1501                                             | 3803           | Wynnwood Dr        | Building        | c 1960      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Medium          |
| PF.M07.S1506                                             | 3815           | Wynnwood Dr        | Building        | c 1963      | Domestic-single      | Fr Colonial Revival | 1              | Brick           | Low             |



























[illegible]

























[illegible]

[illegible]





[illegible]

























[illegible]









[illegible]





[illegible]

[illegible]



















|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |